

# ANNUAL SURVEYS.

No. 41570 Survey held at London Date, first Survey May 19 Last Survey May 26 1882  
 No. in on the SS Eldorado Master Stevenson  
 Reg. Book. 255 Net 2157 Built at Hull When built 1873 Month. 3  
 Tonnage Gross 3332 By whom built Charles & Co Owners A Gray & S Sawes  
 Under Dk. 2128 Port belonging to Glasgow Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock about dry dock (State Name of Dock.)

Last Survey, No. 41179 Port of Low Classed 100 A 282  
SS Lin M2 81  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 General Observations, Opinion as to Class, &c. Bottom & coated.  
She is now in an efficient state and eligible to remain as classed

Committee's Minute Tuesday, 13th June, 1882.  
 Character assigned 100 A 282 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.            Survey held at            Date, first Survey            Last Survey            18            
 No. in on the            Master             
 Reg. Book.            Net            Built at            When built            Year.            Month.             
 Tonnage Gross            By whom built            Owners             
 Under Dk.            Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock            (State Name of Dock.)

Last Survey, No.            Port of            Classed             
 Present Condition of the  
 Decks            Treenails             
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on             
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
 Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18