

ANNUAL SURVEYS.

41583

No. 118 Survey held at London Date, first Survey June 12 Last Survey June 13 1882

No. in Reg. Book. 118 on the Iron Ship "Barossa" Master H. F. Walker
Tonnage { Net 968 Built at Switzerland When built 1873 5
Gross 1019 Under Dk. 885 By whom built W. Pitt and Owners J. B. Walker
Port belonging to London Destined Voyage Whitland
If Surveyed Afloat or in Dry Dock Switzerland dock

Last Survey, No. 4045 Port of Low Classed 100 A. 1
Years assigned. 6-81 Character in Register Book.

Present Condition of the Decks good Treenails mixed good
Breasthooks and Stemson do
Waterways fair Transoms, Pointers, and Crutches do
Comings good Timbers of the Frame at the Openings do
Upper Deck Beams & Fastenings do Ditto ditto at other places do
Lower Deck Beams & Fastenings do Keelsons good
Planksheers none Clamps and Shelves Wings good
Sheerstrakes plated in good Ceiling do
Topsides plated in good Rudder do
Wales plated in good Copper or Y.M. do When put on do
Plank (Bottom) and Counter plated in good Caulking of Bottom, Deck, & Waterways good
Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. This hull was docked, the bottom cleaned and repaired. Lower brace of rudder fitted with white metal. The coil pipes of steamers class now fitted above the deck, and the former holes in the shell plating properly stopped and a blank flange riveted overall. A new fore and after fitted to main hatch.

Committee's Minute Friday, 16th June, 1882.
Character assigned 100 A. 1 J.B.M. Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master
Tonnage { Net Built at When built
Gross By whom built Owners
Under Dk. Destined Voyage
Port belonging to If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Years assigned. Character in Register Book.

Present Condition of the Decks Treenails
Breasthooks and Stemson
Waterways Transoms, Pointers, and Crutches
Comings Timbers of the Frame at the Openings
Upper Deck Beams & Fastenings Ditto ditto at other places
Lower Deck Beams & Fastenings Keelsons
Planksheers Clamps and Shelves
Sheerstrakes Ceiling
Topsides Rudder
Wales Copper or Y.M. When put on
Plank (Bottom) and Counter Caulking of Bottom, Deck, & Waterways
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18



L04608-0312