

ANNUAL SURVEYS.

No. 41585 Survey held at London Date, first Survey 10th June Last Survey 10th June 1882
 No. in on the Siron B^c "Lock Fleet" Master B. Blackie
 Reg. Book. 599 Net 413 Built at Glasgow When built 1872 9
 Tonnage Gross 749 By whom built Robie & Co Owners J. Sproul
 Under Dk. 689 Port belonging to Liverpool Destined Voyage Gu. Island
 If Surveyed Afloat or in Dry Dock West India very black
 (State Name of Dock.)

Last Survey, No. 40720 Port of Low
 Present Condition of the
 Decks Good Treeneils Good Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plate (Bottom) and Counter " Copper or Y.M. Cement When put on 1872
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated.

This vessel is in good condition and in my opinion eligible to remain as classed.

Committee's Minute Friday, 16th June, 1882. Chas. H. Stowell
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 41585 Survey held at London Date, first Survey 10th June Last Survey 10th June 1882
 No. in on the Siron Ship "Wairoa" Master J. Adams
 Reg. Book. 630 Net 1015 Built at Newcastle When built 1875 11
 Tonnage Gross 1057 By whom built Palmer & Co Owners N. Zealand Ship Co. Ltd.
 Under Dk. 805 Port belonging to Lyttleton, N.Z. Destined Voyage Canterbury
 If Surveyed Afloat or in Dry Dock equal very black
 (State Name of Dock.)

Last Survey, No. 40410 Port of Low
 Present Condition of the
 Decks Good Treeneils Good Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plate (Bottom) and Counter " Copper or Y.M. Cement When put on 1875
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated, also pushed the Pintles

This vessel is in good condition and in my opinion eligible to remain as classed.

Committee's Minute Friday, 16th June, 1882. Chas. H. Stowell
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18