

ANNUAL SURVEYS.

41625

No. Survey held at London Date, first Survey June 15 Last Survey June 17th 1882
 No. in on the SS Darlington Master J Hogg
 Reg. Book. 1293
 Tonnage 1880 Built at Newcastle When built 1881. 5
 By whom built Swan & Hunter Owners W. Milburn & Co
 Port belonging to London Destined Voyage Newcastle & Bradford
 If Surveyed Afloat or in Dry Dock Thames & W. Dry Dock

Last Survey, No. 41149 Port of Lon Classed 100A 1882

Present Condition of the			
Planks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stenson	"
Rings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Winksheers	"	Keelsons	"
Overstrakes	"	Clamps and Shelves	"
Stides	"	Ceiling	"
Decks	"	Rudder <u>Some Rivets renewed</u>	"
Stem (Bottom) and Counter	"	Copper or Y.M. <u>Copper</u> When put on <u>new</u>	"
Engine Room Skylights	<u>Good</u>	Caulking of	"
General Observations, Opinion as to Class, &c.	<u>Coal Bunker, Openings, Lids, &c. <u>Good</u> Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good</u></u>		

She is now in an efficient state & eligible to remain as classed.

Committee's Minute Tuesday, 27th June, 1882.

Character assigned J.W. 100A

Senhouse Martin Dale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1882

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book.
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed 18

Present Condition of the			
Planks		Treenails	
Waterways		Breasthooks and Stenson	
Rings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings		Ditto ditto at other places	
Winksheers		Keelsons	
Overstrakes		Clamps and Shelves	
Stides		Ceiling	
Decks		Rudder	
Stem (Bottom) and Counter		Copper or Y.M. <u> </u> When put on <u> </u>	
Engine Room Skylights		Caulking of	
General Observations, Opinion as to Class, &c.	<u>Coal Bunkers, Openings, Lids, &c. <u> </u> Scuppers <u> </u> Cargo and Main Hatchways <u> </u> Hatches <u> </u></u>		

Committee's Minute 18
 Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

