

ANNUAL SURVEYS.

* 41029

No. 86 Survey held at London Date, first Survey June 12 Last Survey July 4 1882
 (Received at London Office, 8.7.82)
 No. in Reg. Book. on the SS Warwick Castle Master Robinson
 (No. of Visits 2)
 Tonnage { Net 1892 Built at Glasgow When built 1879 8
 Gross 2957
 Under Dk. 2867 By whom built R Mappin & Son Owners J Lunn & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock James I W St & Afloat
 (State Name of Dock.)

Last Survey, No. 41329 Port of London Classed 100A1-12-81
 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Rivets	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"			Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"			Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"			Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"			Condition, how ascertained	<u>From St</u>
Planksheers	"	Keelsons	"			Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves	"			Anchors, No. of <u>2 Nos. 12 & 14 lbs</u>	<u>Good</u>
Topsides	"	Ceiling	"			Cables <u>Porter 12</u>	<u>Good</u>
Wales	"	Rudder	"			Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Souled</u> When put on <u>Now</u>				Standing and Running Rigging	"
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>				
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>						
Scuppers	<u>Good</u>						
Cargo and Main Hatchways	<u>Good</u>						
Hatches	"						

General Observations, Opinion as to Class, &c. Bottom &c coated.
She is now in an efficient state and eligible to remain as classed.
She had SS M&I done in last March. As per London Report No. 41329

Committee's Minute Tuesday, 11th July, 1882 Senhouse Masthead
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 (No. of Visits _____)
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Destined Voyage _____
 Port belonging to _____
 If Surveyed Afloat or in Dry Dock _____
 (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. Character in Register Book.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. _____ When put on _____	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.		
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 1 for Annual Survey, when there are no repairs. 4000-26/4/82.)
 (If a survey is made, the surveyor is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

