

ANNUAL SURVEYS.

No. 347 Survey held at London Date, first Survey July 6 Last Survey July 6 1882
 No. in Reg. Book. on the SS Torunda Master Templeton
 Tonnage { Net 1543 Built at Burmburton When built 1875 Month. 10
 Gross 2577
 Under Dk. 2520 By whom built W. Senny & Bros. Owners D. Macneil & P. Senny
 Port belonging to Glasgow Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Albert Dry Dock
 (State Name of Dock.)

Last Survey, No. 41184 Port of London Classed 100A1 2,82
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Brushed
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom be coated.
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Tuesday, 15th July, 1882.
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master
 Tonnage { Net Built at When built Year. Month.
 Gross
 Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18