

# ANNUAL SURVEYS.

41644

No. 154 Survey held at London Date, first Survey June 30 Last Survey July 3 1882  
 (Received at London Office, 8/7/82)  
 No. in Reg. Book. on the Am Am Steamship "Malaga" Master J. Russell  
 Tonnage { Net 1024 Built at West Hartlepool When built 1876 4  
 Gross 1614 By whom built W. Gray & Co. Owners J. Hall, Junr and Co.  
 Under Dk. 1420 Port belonging to London Destined Voyage Lady  
 If Surveyed Afloat or in Dry Dock Agent dock  
 (State Name of Dock.)


Last Survey, No. 40599 Port of London Classed 100 A. 1  
 Present Condition of the  
 Decks good Treennails good  
 Waterways do Breasthooks and Stemson good  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers none Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel was docked to tight the bottom, which was found in good condition, and has now been scraped and renovated. The rudder lifted and further inspected. The chain cables were changed for requirements of the Board of Trade. She is in good condition and eligible to remain as classed.

Committee's Minute Friday, 28th July, 1882.  
 Character assigned 100 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Y Paid 3 Aug 1882

No.        Survey held at        Date, first Survey        Last Survey        18        
 (No. of Visits       )  
 No. in Reg. Book. on the        Master         
 Tonnage { Net        Built at        When built         
 Gross        By whom built        Owners         
 Under Dk.        Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock         
 (State Name of Dock.)

Last Survey, No.        Port of        Classed         
 Present Condition of the  
 Decks        Treennails         
 Waterways        Breasthooks and Stemson         
 Comings        Transoms, Pointers, and Crutches         
 Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings         
 Lower Deck Beams & Fastenings        Ditto ditto at other places         
 Planksheers        Keelsons         
 Sheerstrakes        Clamps and Shelves         
 Topsides        Ceiling         
 Wales        Rudder         
 Plank (Bottom) and Counter        Copper or Y.M.        When put on         
 Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
 General Observations, Opinion as to Class, &c.       

Committee's Minute        18        
 Character assigned        Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)        Paid        18      



L0N668-0463

(If a Steam Ship, state if a Report is also sent on the Machinery...)

(Insert Character precisely as in Register Book.)