

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey June 22 Last Survey July 22 1882

No. in Reg. Book. 216 on the S. Harwar Master
 Tonnage { Net 1300 Built at Belfast When built 1864 Month. 3
 { Gross 1456 By whom built Harland Owners J. Mills
 { Under Dk. 1214 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Greens Bay NW afloat
 (State Name of Dock.)

Last Survey, No. 40261 Port of Low Classed A 1 381
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Good Treenails Pivots Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Pushed "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "

General Observations, Opinion as to Class, &c. Bottom & copper, Rudder pushed
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday, 28th July, 1882. Senhouse Martindale

Character assigned A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master
 Tonnage { Net Built at When built Year. Month.
 { Gross By whom built Owners
 { Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid

