

ANNUAL SURVEYS.

41637

(Received at London Office, 9887)

No. Survey held at London Date, first Survey 1 Augr Last Survey 3 Augr 1882

No. in Reg. Book. 586 on the SS Sikh Master Johnson (No. of Visits 2)

Tonnage Net 1510 Built at Glasgow When built 1880 11 Month.

By whom built Aitken & Co Owners Gallalley & Co

Port belonging to Glasgow Destined Voyage Australia

If Surveyed Afloat or in Dry Dock Pontoon Victoria St (State Name of Dock.)

Last Survey, No. 28841 Port of London Classed 100A.12.80

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stenson	<u>"</u>	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Windlass and Capstan <u>Good</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Boats <u>"</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Masts, Yards, &c. <u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Condition, how ascertained <u>From St</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Sails <u>Good</u>
Wales	<u>"</u>	Rudder <u>Broken</u>	<u>"</u>	Anchors, No. of <u>3 Bro. St & Rodys</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. <u>Broken</u> When put on <u>new</u>	<u>"</u>	Cables <u>Part on St</u> <u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Hawsers and Warps <u>"</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>			Standing and Running Rigging <u>"</u>
Scuppers	<u>Good</u>			
Cargo and Main Hatchways	<u>Good</u>			
Hatches	<u>"</u>			

General Observations, Opinion as to Class, &c. Bottom coated. After end of garboard stake plate caulked. New Propeller. She is now in an efficient state & eligible to remain as classed.

Committee's Minute Tuesday, 22nd August, 1882. Senhouse Martindale

Character assigned 100A J.M. Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master (No. of Visits)

Tonnage Net Built at When built Month.

By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the Decks	<u> </u>	Treenails	<u> </u>	
Waterways	<u> </u>	Breasthooks and Stenson	<u> </u>	Windlass and Capstan <u> </u>
Comings	<u> </u>	Transoms, Pointers, and Crutches	<u> </u>	Pumps <u> </u>
Upper Deck Beams & Fastenings	<u> </u>	Timbers of the Frame at the Openings	<u> </u>	Boats <u> </u>
Lower Deck Beams & Fastenings	<u> </u>	Ditto ditto at other places	<u> </u>	Masts, Yards, &c. <u> </u>
Planksheers	<u> </u>	Keelsons	<u> </u>	Condition, how ascertained <u> </u>
Sheerstrakes	<u> </u>	Clamps and Shelves	<u> </u>	Sails <u> </u>
Topsides	<u> </u>	Ceiling	<u> </u>	Anchors, No. of <u> </u>
Wales	<u> </u>	Rudder	<u> </u>	Cables <u> </u>
Plank (Bottom) and Counter	<u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	<u> </u>	Hawsers and Warps <u> </u>
Engine Room Skylights	<u> </u>	Caulking of Bottom, Deck, & Waterways	<u> </u>	Standing and Running Rigging <u> </u>
Coal Bunkers, Openings, Lids, &c.	<u> </u>			
Scuppers	<u> </u>			
Cargo and Main Hatchways	<u> </u>			
Hatches	<u> </u>			

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery.) (Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

