

ANNUAL SURVEYS.

* 47660

(Received at London Office, 15/8/82)

No. _____ Survey held at London Date, first Survey July 8th Last Survey Sept 15th 1882
 (No. of Visits 2)
 No. in on the SS Drummond Castle Master Manchester
 Reg. Book. 401 Net 2381 Built at Glasgow When built 1881 Year. _____ Month. _____
 Tonnage } Gross 3705 By whom built J Elder & Co Owners S Currie & Co
 Under Dk. 3537
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock James J W Loch & Co (State Name of Dock.) _____

Last Survey, No. 41389 Port of London Classed 100A 4.82

Present Condition of the Decks	<u>Good</u> Treenails <u>Rivets</u> <u>Good</u>	
Waterways	Breasthooks and Stemson	Windlass and Capstan <u>Good</u>
Comings	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats
Lower Deck Beams & Fastenings	Ditto ditto at other places	Masts, Yards, &c.
Planksheers	Keelsons	Condition, how ascertained <u>Exam'd</u>
Sheerstrakes	Clamps and Shelves	Sails <u>Good</u>
Topsides	Ceiling	Anchors, No. of <u>3 Bm 12 & 12</u>
Wales	Rudder	Cables <u>Exam'd</u>
Plank (Bottom) and Counter	Copper or Y.M. Coated When put on <u>none</u>	Hawsers and Warps
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
		Hatches <u>4</u>

General Observations, Opinion as to Class, &c. Bottom & coated
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, 22nd August, 1882. Senhouse Martindale
 Character assigned 100A DRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 (No. of Visits _____)
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage } Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Destined Voyage _____
 Port belonging to _____
 If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.) _____

Last Survey, No. _____ Port of _____ Classed _____

Present Condition of the Decks	Treenails	
Waterways	Breasthooks and Stemson	Windlass and Capstan
Comings	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats
Lower Deck Beams & Fastenings	Ditto ditto at other places	Masts, Yards, &c.
Planksheers	Keelsons	Condition, how ascertained
Sheerstrakes	Clamps and Shelves	Sails
Topsides	Ceiling	Anchors, No. of
Wales	Rudder	Cables
Plank (Bottom) and Counter	Copper or Y.M. When put on	Hawsers and Warps
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
		Hatches

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

