

# ANNUAL SURVEYS.

41661

No. 1077 Survey held at London Date, first Survey July 4<sup>th</sup> Last Survey August 8<sup>th</sup> 1882  
 No. in Reg. Book. on the Iron Ship "Connaught Ranger" Master S. Williams  
 Tonnage 1153 Built at Belfast When built 1875 - 8  
 Under Dk. 1109 By whom built Harland & Wolff Owners Merchant Ship Co. Ltd.  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Canal dry Dock and afloat  
 (State Name of Dock.)

Last Survey, No. 40191 Port of London Classed 100 A 1  
 Present Condition of the  
 Decks good Treanails Rivets good S.S. H. Kg No. 1-79 3, 81  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1875  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has now been placed in dry Dock the bottom examined and recoated with White Zinc and Yellow. A Donkey Boiler fitted in deck house and a Steam Winch at Aftside of Main Hatch. She is now in good and efficient condition and eligible in my opinion to remain as classed

Committee's Minute Tuesday, 22nd August, 18 82.  
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 564 Survey held at London Date, first Survey July 13<sup>th</sup> Last Survey July 21<sup>st</sup> 1882  
 No. in Reg. Book. on the Iron Bt. "Lock Ur" Master S. Murodock  
 Tonnage 716 Built at Port Glasgow When built 1870 - "  
 Under Dk. 696 By whom built McAlloch, Patterson & Co. Owners J. Sproat  
 Port belonging to Liverpool Destined Voyage Auckland N.Z.  
 If Surveyed Afloat or in Dry Dock West India dry Dock and afloat  
 (State Name of Dock.)

Last Survey, No. 40673 Port of London Classed 100 A 1  
 Present Condition of the  
 Decks good Treanails Rivets good S.S. Lm No. 2-79 7, 81  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1870  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. This vessel is now in good and efficient condition and eligible in my opinion to remain as classed

Committee's Minute Tuesday, 22nd August, 18 82.  
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18