

ANNUAL SURVEYS.

41663

No. 108 Survey held at London Date, first Survey Aug 9th Last Survey Aug 10th 1882
 (Received at London Office, 17-8-82)
 No. in Reg. Book. 108 on the San Juan Maria Felice Amariani Master W. Johnston
 (No. of Visits 2)
 Tonnage ^{Net} 1067 Built at New York When built 1881 Month 2
^{Gross} 1638
^{Under Dk.} 1579 By whom built Polissin Co Owners J and R Bony
 Port belonging to London Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock London by 4th
 (State Name of Dock.)

Last Survey, No. 1178 Port of Dumb Classed 100 A. 1
 Years assigned. 4 82 Character in Register Book.
 Present Condition of the Decks Good Treenails Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches Good Windlass and Capstan Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings do Pumps do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Boats do
 Plank sheers do Keelsons Good Masts, Yards, &c. do
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from drill
 Topsides do Ceiling do Sails Complete
 Wales do Rudder do Anchors, No. of 3 B 14. 2 1/2
 Plank (Bottom) and Counter do Copper or Y.M. When put on Cables not ranged
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. This vessel was docked the bottom sighted, scraped and recoated, being in good order and condition she is eligible in my opinion to remain as classed.

Committee's Minute 22/8/82 18
 Character assigned 100 A. 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 (No. of Visits _____)
 No. in Reg. Book. _____ on the _____ Master _____
 (Year. _____ Month. _____)
 Tonnage ^{Net} _____ Built at _____ When built _____
^{Gross} _____ By whom built _____ Owners _____
^{Under Dk.} _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
 (State Name of Dock.)
 Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. _____ Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Plank sheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

