

ANNUAL SURVEYS.

411666

No. in on the Iron Ship "Carbet Castle" Master Davies
 g. Book. 216 (Net 1585 Built at Sunderland When built 1875 - 7 Month.
 Tonnage Gross 1649 Under Dk. 1469 By whom built Mouney & Foster Owners L. H. Mac Intyre & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Ruggi dry Dock and Afloat
 (State Name of Dock.)

Last Survey, No. 28316 Port of Liverpool Classed 100 A 1
 Present Condition of the
 Decks good Treenails Pivots good S. S. Liv No 1-80 9, 80
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1875
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom examined and recoated with Paint. This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 18
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 27706 Survey held at Liverpool Date, first Survey July 28th Last Survey August 31st 1882
 No. in on the Iron Bth "Lillegro" Master Trew
 Reg. Book. 595 (Net 595 Built at Liverpool When built 1868 - 5 Month.
 Tonnage Gross 612 Under Dk. 581 By whom built J. Roydon & Sons Owners J. Roydon & Sons
 Port belonging to Liverpool Destined Voyage West Coast of Africa via Cardiff
 If Surveyed Afloat or in Dry Dock Ruggi dry Dock
 (State Name of Dock.)

Last Survey, No. 27706 Port of Liverpool Classed * A 1
 Present Condition of the
 Decks good Treenails Pivots good S. S. Liv No 3-81 6, 81
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder planks lashed
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1868
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom recoated with Paint & Rudder lashed. This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 18
 Character assigned * A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON 668-0509