

# ANNUAL SURVEYS.

41669

No. 521 Survey held at London Date, first Survey 5 June Last Survey July 31<sup>st</sup> 1882  
(Received at London Office, 1-8-82)  
No. in Reg. Book. on the S Shannon Master V Stepiak (No. of Visits 2)  
Tonnage { Net 178 Built at London When built 1862 Year. 5 Month.   
Gross 1282  
Under Dk. 1282 By whom built R & H Green Owners R & H Green  
Port belonging to London Destined Voyage Australia  
If Surveyed Afloat or in Dry Dock Green Dry Dock & Afloat (State Name of Dock.)

Last Survey, No. 40725 Port of London  
Present Condition of the  
Decks Good Treenails Good  
Waterways " Breasthooks and Stemson "  
Comings " Transoms, Pointers, and Crutches "  
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
Lower Deck Beams & Fastenings " Ditto ditto at other places "  
Planksheers " Keelsons "  
Sheerstrakes " Clamps and Shelves "  
Topsides " Ceiling "  
Wales " Rudder "  
Plank (Bottom) and Counter " Copper or Y.M. 3 Metallo When put on 1880  
Engine Room Skylights " Caulking of Patched now  
Bottom, Deck, & Waterways Good  
Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "  
General Observations, Opinion as to Class, &c. She is now in an efficient state and eligible to remain as classed

Committee's Minute

Friday, 4th August, 1882.

Senhouse Martindale

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No.  Survey held at  Date, first Survey  Last Survey  18  
(No. of Visits )  
No. in Reg. Book. on the  Master  Year.  Month.   
Tonnage { Net  Built at  When built   
Gross  By whom built  Owners   
Under Dk.   
Port belonging to  Destined Voyage   
If Surveyed Afloat or in Dry Dock  (State Name of Dock.)

Last Survey, No.

Port of

Classed

Present Condition of the  
Decks  Treenails   
Waterways  Breasthooks and Stemson   
Comings  Transoms, Pointers, and Crutches   
Upper Deck Beams & Fastenings  Timbers of the Frame at the Openings   
Lower Deck Beams & Fastenings  Ditto ditto at other places   
Planksheers  Keelsons   
Sheerstrakes  Clamps and Shelves   
Topsides  Ceiling   
Wales  Rudder   
Plank (Bottom) and Counter  Copper or Y.M.  When put on   
Engine Room Skylights  Caulking of   
Bottom, Deck, & Waterways   
Coal Bunkers, Openings, Lids, &c.  Scuppers  Cargo and Main Hatchways  Hatches   
General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON 668-0515