

ANNUAL SURVEYS.

*41676

(Received at London Office, _____)

No. 546 Survey held at London Date, first Survey 12 Aug Last Survey Aug 16 1882
 No. in on the S Lock Sunke Master P. Mendrough
 Reg. Book. 546 (No. of Visits 1)
 Tonnage 1381 Net Built at Glasgow When built 1876 12 Month.
1468 Gross By whom built J. J. Thomson Owners J. J. O. Nelson
1322 Under Dk. Port belonging to Glasgow Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Green St
(State Name of Dock.)

[Handwritten signature]

Last Survey, No. 40954 Port of London Classed 100A 7.80
Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u> Treennails <u>Rivets</u>	<u>Good</u>
Waterways	Breasthooks and Stemson	"
Comings	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	Ditto ditto at other places	"
Planksheers	Keelsons	"
Sheerstrakes	Clamps and Shelves	"
Topsides	Ceiling	"
Wales	Rudder	"
Plank (Bottom) and Counter	Copper or Y.M. <u>Cooked</u> When put on <u>Alloy</u>	"
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	Scuppers	<u>Good</u>
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways	<u>Good</u>
	Hatches	"
	Windlass and Capstan	<u>Good</u>
	Pumps	"
	Boats	"
	Masts, Yards, &c.	"
	Condition, how ascertained	<u>From St</u>
	Sails	<u>Good</u>
	Anchors, No. of <u>1 No. 12 1 No. 8</u>	"
	Cables <u>Part on St</u>	<u>Good</u>
	Hawsers and Warps	"
	Standing and Running Rigging	"

Bottom is coated
 She is now in an efficient state and eligible to remain as classed, and when the Special Fee £5-5-0 is paid to have 88000 reg-1881 recorded carry under the survey last year as per Report attached


Committee's Minute Tuesday, 20th August, 18 82.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 18 82

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ (No. of Visits _____)
 Tonnage 1381 Net Built at _____ When built _____
1468 Gross By whom built _____ Owners _____
1322 Under Dk. Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks	Treennails	
Waterways	Breasthooks and Stemson	
Comings	Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings	Ditto ditto at other places	
Planksheers	Keelsons	
Sheerstrakes	Clamps and Shelves	
Topsides	Ceiling	
Wales	Rudder	
Plank (Bottom) and Counter	Copper or Y.M. _____ When put on _____	
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.	Scuppers	
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways	
	Hatches	
	Windlass and Capstan	
	Pumps	
	Boats	
	Masts, Yards, &c.	
	Condition, how ascertained	
	Sails	
	Anchors, No. of _____	
	Cables	
	Hawsers and Warps	
	Standing and Running Rigging	

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18____



The Surveyors are requested not to write on or below the space for Committee's Minute, when there are no repairs.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.