

ANNUAL SURVEYS.

(Received at London Office,

No. _____ Survey held at London Date, first Survey 4 August Last Survey 21 August 1882
(No. of Visits 3)
No. in Reg. Book. on the SS Viceroy Master _____ Year. _____ Month. _____
Tonnage { Net 1866 Built at London When built 1877
Gross 2463 By whom built R & H Green Owners R & H Green
Under Dk. 2301 Port belonging to London Destined Voyage not known
If Surveyed Afloat or in Dry Dock Greens Dry Dock (State Name of Dock.)

Last Survey, No. 40568 Port of Low Classed 100A 11.81
Present Condition of the Decks good Treenails Rivets good
Breasthooks and Stemson good
Waterways good Transoms, Pointers, and Crutches good Windlass and Capstan good
Comings good Timbers of the Frame at the Openings good Pumps good
Upper Deck Beams & Fastenings good Ditto ditto at other places good Boats good
Lower Deck Beams & Fastenings good Keelsons good Masts, Yards, &c. good
Planksheers good Clamps and Shelves good Condition, how ascertained from SK
Sheerstrakes good Ceiling good Sails good
Topsides good Rudder good Anchors, No. of 3 Pers. SK & Reddy
Wales good Copper or Y.M. Coated When put on now Cables Part on SK good
Plank (Bottom) and Counter good Caulking of Bottom, Deck, & Waterways good Hawsers and Warps good
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. Bottom ke coated.
She is now in an efficient state and eligible to remain as classed.

Committee's Minute 100A Tuesday, 29th August, 1882 Lombhouse Martindale
Character assigned B. S. P. 82 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at Quebec to 10 Date, first Survey _____ Last Survey _____ 18 _____
(No. of Visits _____)
No. in Reg. Book. on the _____ Master _____ Year. _____ Month. _____
Tonnage { Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____ Destined Voyage _____
Port belonging to _____
If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)
Last Survey, No. _____ Port of _____ Classed _____
Present Condition of the Decks _____ Treenails _____
Breasthooks and Stemson _____
Waterways _____ Transoms, Pointers, and Crutches _____
Comings _____ Timbers of the Frame at the Openings _____
Upper Deck Beams & Fastenings _____ Ditto ditto at other places _____
Lower Deck Beams & Fastenings _____ Keelsons _____
Planksheers _____ Clamps and Shelves _____
Sheerstrakes _____ Ceiling _____
Topsides _____ Rudder _____
Wales _____ Copper or Y.M. _____ When put on _____
Plank (Bottom) and Counter _____ Caulking of Bottom, Deck, & Waterways _____
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
Character assigned _____
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

