

# ANNUAL SURVEYS.

41685  
3882

No. 44 Survey held at London Date, first Survey July 27 Last Survey July 27 18 82  
(Received at London Office, ...)  
(No. of Visits ...)  
 No. in Reg. Book. 44 on the Steamer Alicia Master Robinson  
Year. Month.  
 Tonnage 499 Net Built at Northfleet When built 1866  
784 Gross By whom built Richardson & Co. Owners  
674 Under Dk. J. Hall Jun<sup>r</sup> and Co  
 Port belonging to London Destined Voyage South Sea  
 If Surveyed Afloat or in Dry Dock Regent Dock  
(State Name of Dock.)

Last Survey, No. 40491 Port of London Classed A 1  
Years assigned. Character in Register Book.  
 Present Condition of the Decks good Treenails good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches good  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers good Keelsons do  
 Sheerstrakes good Clamps and Shelves good  
 Lopsides good Ceiling do  
 Wales good Rudder do  
 Plank (Bottom) and Counter good Copper or Y.M. do When put on do  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. How does the bottom appear & is it sound?  
A new propeller fitted. Being in good condition the vessel is eligible  
in my opinion to remain as classed

Committee's Minute Friday, 11th August, 18 82.  
 Character assigned A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
(No. of Visits ...)  
 No. in Reg. Book. \_\_\_\_\_ on the \_\_\_\_\_ Master \_\_\_\_\_  
Year. Month.  
 Tonnage \_\_\_\_\_ Net Built at \_\_\_\_\_ When built \_\_\_\_\_  
 \_\_\_\_\_ Gross By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 \_\_\_\_\_ Under Dk. \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 Port belonging to \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
Years assigned. Character in Register Book.  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Surveys. 4000-2674. There are no repairs. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

