

ANNUAL SURVEYS.

* 41686

No. 443 on the Ann Steamer Aston Survey held at London Date, first Survey July 15 Last Survey July 13 1882
 Reg. Book. 443 Master J. H. Hall (No. of Visits 7)
 Tonnage { Net 860 Built at West Hartlepool When built 1871
 Gross 1334 By whom built Stanton & Co. Owners J. Hall, Junr and Co.
 Under Dk. 1294 Port belonging to London Destined Voyage for the
 If Surveyed Afloat or in Dry Dock in Dry Dock (State Name of Dock.)

Last Survey, No. 40541 Port of London Classed 100 A.1
 Years assigned. 6.81 Character in Register Book.

Present Condition of the Decks good Treenails new good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers new Keelsons do
 Sheerstrakes do Clamps and Shelves strong do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Made annual survey, sighted the bottom, which has never been cleaned and resurfaced, and being in good & efficient condition this vessel is eligible to remain as classed

Committee's Minute

Friday, 14th August, 1882.

Character assigned

100A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 443 Survey held at London Date, first Survey July 15 Last Survey July 13 1882
 Reg. Book. 443 Master J. H. Hall (No. of Visits 7)
 Tonnage { Net 860 Built at West Hartlepool When built 1871
 Gross 1334 By whom built Stanton & Co. Owners J. Hall, Junr and Co.
 Under Dk. 1294 Port belonging to London Destined Voyage for the
 If Surveyed Afloat or in Dry Dock in Dry Dock (State Name of Dock.)

Last Survey, No. 40541 Port of London Classed 100 A.1
 Years assigned. 6.81 Character in Register Book.

Present Condition of the Decks good Treenails new good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers new Keelsons do
 Sheerstrakes do Clamps and Shelves strong do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Made annual survey, sighted the bottom, which has never been cleaned and resurfaced, and being in good & efficient condition this vessel is eligible to remain as classed

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON668-0560