

ANNUAL SURVEYS.

41692

No. 130 Survey held at London Date, first Survey June 4th Last Survey July 28th 1882
 No. in on the Iron Ship "Nereus" Master Worledge
 Reg. Book. 130 Net 1068 Built at Liverpool When built 1868 - 94
 Tonnage Gross 1108 Under Dk. 988 By whom built Bowdler, Chaffers & Co Owners W. J. Myers, Son & Co
 Port belonging to Liverpool Destined Voyage Otago
 If Surveyed Afloat or in Dry Dock Poplar dry Dock and Afloat
(State Name of Dock.)

Last Survey, No. 27493 Port of Lid Classed S.S. Liv No 3-81 Character in Register Book. *A 1
 Present Condition of the Decks good Treenails Rivets good Years assigned. 3, 81

Waterways	good	Breasthooks and Stemson	good	Windlass and Capstan	good
Comings	"	Transoms, Pointers, and Crutches	"	Pumps	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c.	"
Planksheers	"	Keelsons	"	Condition, how ascertained	by observation
Sheerstrakes	"	Clamps and Shelves	"	Sails	Sufficient
Topsides	"	Ceiling	"	Anchors, No. of	3 B, 1 S & 2 K
Wales	"	Rudder	"	Cables	part seen on deck good
Plank (Bottom) and Counter	"	Copper or Y.M. Cemented When put on	1868	Haulsers and Warps	Sufficient
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	good	Standing and Running Rigging	"
Coal Bunkers, Openings, Lids, &c.		Scuppers	good	Cargo and Main Hatchways	good
Hatches	good				

General Observations, Opinion as to Class, &c. This vessel has now been placed in dry dock the bottom examined and regated with Paint, the Rudder painted bushed, and the plates in each of the lower topsail yard arms renewed. She is now in good and efficient condition and eligible in my opinion to remain and classed. The vessel is now worked as a B.C. the yards having been removed from the Mizzen Mast.
 Tuesday, 15th August, 1882.
 Committee's Minute _____
 Character assigned *A 1 Surveyor to Lloyd's Register of British and Foreign Shipping. J. W. Miles
 Certificate (if required, to be sent as per margin) Paid 18

No. 25 Survey held at London Date, first Survey June 28th Last Survey July 25th 1882
 No. in on the Iron Ship "Wairimate" Master Richard Mosey
 Reg. Book. 25 Net 1124 Built at Sunderland When built 1874 - 8
 Tonnage Gross 1156 Under Dk. 1016 By whom built J. Blumer & Co Owners New Zealand Ship Co
 Port belonging to Lyttelton N.Z. Destined Voyage Canterbury
 If Surveyed Afloat or in Dry Dock Canal dry Dock and Afloat
(State Name of Dock.)

Last Survey, No. 40806 Port of London Classed S.S. Lond No 1-79 Character in Register Book. 100 A 1
 Present Condition of the Decks good Treenails Rivets good Years assigned. 9, 81

Waterways	good	Breasthooks and Stemson	good	Windlass and Capstan	good
Comings	"	Transoms, Pointers, and Crutches	"	Pumps	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c.	"
Planksheers	"	Keelsons	"	Condition, how ascertained	by observation
Sheerstrakes	"	Clamps and Shelves	"	Sails	Sufficient
Topsides	"	Ceiling	"	Anchors, No. of	3 B, 1 S & 2 K
Wales	"	Rudder	"	Cables	part seen on deck good
Plank (Bottom) and Counter	"	Copper or Y.M. Cemented When put on		Haulsers and Warps	Sufficient
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	good	Standing and Running Rigging	"
Coal Bunkers, Openings, Lids, &c.		Scuppers	good	Cargo and Main Hatchways	good
Hatches	good				

General Observations, Opinion as to Class, &c. The bottom has now been examined and recoated with Paint and the Rudder painted bushed. The timber boards lifted and the floor cement washed. One mainmast, upper & lower topsail, foretopmast staysail, and inner fit now new. This vessel is now in good and efficient condition and eligible in my opinion to remain and classed.
 Tuesday, 15th August, 1882.
 Committee's Minute _____
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping. J. W. Miles
 Certificate (if required, to be sent as per margin) Paid 18

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 400 for Annual Survey, when there are no repairs. 400-6/12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)