

ANNUAL SURVEYS.

(Received at London Office, 2/9/82)

No. _____ Survey held at London Date, first Survey 31 August Last Survey 31 August 1882

No. in Reg. Book. 1265 on the SS Austral Master J. Murdoch (No. of Visits 1) Year. _____ Month. _____

Tonnage { Net 2285 Built at Glasgow When built 1881
Gross 5588 By whom built J. Elder & Co Owners Orient Steam Nav Co
Under Dk. 5315

Port belonging to Glasgow Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock Albert Dry Dock (State Name of Dock.)

Last Survey, No. 5693 Port of Gls. Classed 100 A. 4. 82 Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks	<u>grd</u>	Treenails <u>Diets</u>	<u>grd</u>	Windlass and Capstan	<u>grd</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Condition, how ascertained	<u>grd</u>
Planksheers	"	Keelsons	"	Sails	<u>grd</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors, No. of <u>4 No. 12 & 14</u>	<u>grd</u>
Topsides	"	Ceiling	"	Cables <u>Part on gr</u>	<u>grd</u>
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>now</u>	"	Standing and Running Rigging	"
Engine Room Skylights	<u>grd</u>	Caulking of Bottom, Deck, & Waterways	<u>grd</u>	Cargo and Main Hatchways	<u>grd</u>
Coal Bunkers, Openings, Lids, &c.	<u>grd</u>	Scuppers	<u>grd</u>	Hatches	"

General Observations, Opinion as to Class, &c. Bottom &c coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 8th September, 18 82. Senhouse Martindale

Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____

No. in Reg. Book. _____ on the _____ Master _____ (No. of Visits _____) Year. _____ Month. _____

Tonnage { Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____

Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors, No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper or Y.M. _____ When put on _____		Standing and Running Rigging	
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		Cargo and Main Hatchways	
Coal Bunkers, Openings, Lids, &c.		Scuppers		Hatches	

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____

Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-2 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

