

ANNUAL SURVEYS.

41731

No. 1023 Survey held at London Date, first Survey 4 Sept Last Survey Sept 11 1882
 No. in on the 5 Sheathearn Master Grosart
 Reg. Book. 1023 Net 1705 Built at Glasgow When built 1879 9
 Tonnage Gross 1784 Under Dk. 1625 By whom built Barday, Luke & Co Owners J & A Allan
 Port belonging to Glasgow Destined Voyage Cardiff & Rangoon
 If Surveyed Afloat or in Dry Dock Blackwall Pt. Dry Dock & Afloat
(State Name of Dock.)

Last Survey, No. 28321 Port of Liv
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom & counter She is now in an efficient state and eligible to remain as classed.

Years assigned. 100 A-1 70.81
 Character in Register Book. SS Bly M 2.80

Committee's Minute Friday, 15th September, 1882. Senhouse Martindale
 Character assigned 100 A-1 JBM Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 41731 Survey held at London Date, first Survey 7th Sept Last Survey Sept 13 18
 No. in on the 5 Agnes Oswald Master McGibbon
 Reg. Book. 228 Net 1380 Built at Glasgow When built 1876 5
 Tonnage Gross 1447 Under Dk. 1314 By whom built H Murray & Co Owners S Law
 Port belonging to Glasgow Destined Voyage Capetown
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock
(State Name of Dock.)

Last Survey, No. 28688 Port of Liv
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Brushed
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom & counter & Rudder Brushed She is now in an efficient state and eligible to remain as classed.

Years assigned. 100 A-1 11.80
 Character in Register Book. SS Liv M 1.80

Committee's Minute Friday, 15th September, 1882. Senhouse Martindale
 Character assigned 100 A-1 JBM Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 4000-6/12/80. The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book. LON 669-0015

