

# ANNUAL SURVEYS.

41749  
19/9/82

(Received at London Office)

No. 0. Survey held at London Date, first Survey Aug Last Survey 13<sup>th</sup> Sept 1882  
 No. in Reg. Book. 95 on the S. "Her Majesty" Master Deane  
 Tonnage { Net 1104 Built at Calcutta When built 1856 Year. Month.  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners J & R Grant  
 Under Dk. \_\_\_\_\_  
 Port belonging to London Destined Voyage Algoa Bay  
 If Surveyed Afloat or in Dry Dock Reput dry dock (State Name of Dock.)

Last Survey, No. 40823 Port of London Classed 17A 1 9.81  
 Present Condition of the Decks Good Treenails Good  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places Not seen  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter Not seen Copper or Y.M. Y.S. When put on 9/81  
 Engine Room Skylights \_\_\_\_\_ Caulking of Bottom, Deck, & Waterways Good  
 Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.  
She appears as far as seen in good condition and eligible in my opinion to continue as classed

Wm C. Davy  
CEB

Committee's Minute Friday, 22nd September, 1882.  
 Character assigned Good 11 1/2 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 No. in Reg. Book. \_\_\_\_\_ on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Under Dk. \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-20/4/82. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery)

Insert Character precisely as in Register Book. LON 669-0040

