

ANNUAL SURVEYS.

41777
25/9/82
1882

No. _____ Survey held at London Date, first Survey 14 Sept Last Survey Sept 1882
(Received at London Office)
 No. in Reg. Book. 364 on the SS Glenarn Master R.A. Donaldson
(No. of Visits 2)
 Tonnage { Net 1286 Built at Glasgow When built 1881 Month. 2
 Gross 2985
 Under Dk. 2696 By whom built Glasgow Owners McGregor & Co
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Greens Dry Dock
(State Name of Dock.)

Last Survey, No. 41188 Port of Lon Classed 100 A-282
Years assigned. Character in Register Book.

Present Condition of the
 Decks good Treennails good Rivets good
 Waterways good Breasthooks and Stenson good
 Comings good Transoms, Pointers, and Crutches good Windlass and Capstan good
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good Pumps good
 Lower Deck Beams & Fastenings good Ditto ditto at other places good Boats good
 Planksheers good Keelsons good Masts, Yards, &c. good
 Sheerstrakes good Clamps and Shelves good Condition, how ascertained From St
 Topsides good Ceiling good Sails good
 Wales good Rudder good Anchors, No. of 3 No. 12 & 16 lbs
 Plank (Bottom) and Counter good Copper or Y.M. Coated When put on now Cables Part on deck good
 Caulking of Bottom, Deck, & Waterways good Hawsers and Warps good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom & Coated. She is now an efficient state and eligible to remain as classed.

Committee's Minute Friday, 29th September, 1882. Senhouse Martinlake
 Character assigned 100 A-282 JTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
(No. of Visits _____)
 No. in Reg. Book. _____ on the _____ Master _____
Year. Month.
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the
 Decks _____ Treennails _____ Rivets _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____ Windlass and Capstan _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Pumps _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Boats _____
 Planksheers _____ Keelsons _____ Masts, Yards, &c. _____
 Sheerstrakes _____ Clamps and Shelves _____ Condition, how ascertained _____
 Topsides _____ Ceiling _____ Sails _____
 Wales _____ Rudder _____ Anchors, No. of _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Cables _____
 Caulking of Bottom, Deck, & Waterways _____ Hawsers and Warps _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 4000-2614/82.)
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)

