

ANNUAL SURVEYS.

41778
RECEIVED 23 SEP 82

No. Survey held at London Date, first Survey September Last Survey 22nd Sept^r 1882
 (Received at London Office,)

No. in Reg. Book. 632 on the Barque "Griqua" Master A. Dugman
 (No. of Visits 3)

Tonnage Net 309 Built at Alloa When built 1873 Month 7th
Gross 323 By whom built Roy Owners Bullard, King & Co
Under Dk. 275 Port belonging to London Destined Voyage Natal.
 If Surveyed Afloat or in Dry Dock In the Horseferry Dry Dock.
 (State Name of Dock.)

Last Survey, No. 40712 Port of Low

Present Condition of the	Classed	Years assigned.	Character in Register Book.
Decks <u>good</u>	<u>H.T. Lon. 78</u>	<u>10</u>	<u>A.1.</u>
Waterways <u>Do</u>			
Comings <u>Do</u>			
Upper Deck Beams & Fastenings <u>Do</u>			
Lower Deck Beams & Fastenings <u>Do</u>			
Planksheers <u>Do</u>			
Sheerstrakes <u>Do</u>			
Topsides <u>Do</u>			
Wales <u>Do</u>			
Plank (Bottom) and Counter <u>Do</u>			
Engine Room Skylights <u>Do</u>			
Coal Bunkers, Openings, Lids, &c. <u>Do</u>			
Scuppers <u>good</u>			
Cargo and Main Hatchways <u>good</u>			
Hatches <u>good</u>			

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock; the bottom sighted and the yellow metal sheathing repaired where necessary. One plank of the topsides on the port side amidships has now been renewed of pitch pine. The timbers &c. in way of this plank have been examined and found in good condition. This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute Friday, 29th September, 1882.
 Character assigned 10 J.H.W.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at London Date, first Survey 26th Sept^r Last Survey 26th Sept^r 1882
 (Received at London Office,)

No. in Reg. Book. 735 on the Ship "Ann Duthie" Master G. Morgan
 (No. of Visits 1)

Tonnage Net 994 Built at Aberdeen When built 1868 Month 7th
Gross 1051 By whom built Duthie Owners W. Duthie
Under Dk. 884 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock In the Princes Dry Dock
 (State Name of Dock.)

Last Survey, No. 39948 Port of Low

Present Condition of the	Classed	Years assigned.	Character in Register Book.
Decks <u>good</u>	<u>H.T. Lon. 75</u>	<u>17</u>	<u>A.1</u>
Waterways <u>Do</u>			
Comings <u>Do</u>			
Upper Deck Beams & Fastenings <u>Do</u>			
Lower Deck Beams & Fastenings <u>Do</u>			
Planksheers <u>Do</u>			
Sheerstrakes <u>Do</u>			
Topsides <u>Do</u>			
Wales <u>Do</u>			
Plank (Bottom) and Counter <u>Do</u>			
Engine Room Skylights <u>Do</u>			
Coal Bunkers, Openings, Lids, &c. <u>Do</u>			
Scuppers <u>good</u>			
Cargo and Main Hatchways <u>good</u>			
Hatches <u>good</u>			

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock; the bottom sighted and the yellow metal sheathing repaired in a few places where necessary. Vessel surveyed with some iron kentledge in the hold. She is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, 29th September, 1882.
 Character assigned 17 J.H.W.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute...)
 (Form No. 3 for Annual...)
 when there are no repairs. 4000-26/4/82.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 LON 669-0072

