

ANNUAL SURVEYS.

41781
15/9/82

No. Survey held at London Date, first Survey 2 Sept Last Survey 13th Sept 1882
(Received at London Office.)
No. in on the SS Garth Castle Master M. Webster
Reg. Book. 101 (No. of Visits)
Tonnage { Net 2381 Built at Glasgow When built 1880 Year. Month. 12
Gross 3705
Under Dk. 3537 By whom built J. Elder & Co Owners J. Currie & Co
Port belonging to London Destined Voyage Cape
If Surveyed Afloat or in Dry Dock Thames & W. Dock & afloat.
(State Name of Dock.)

Last Survey, No. 41255 Port of Low

Classed 100 A 2.82
Years assigned. Character in Register Book.

Present Condition of the
Decks Good Treenails Rivets Good
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. Coated When put on Now
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
General Observations, Opinion as to Class, &c. Bottom & coated.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 29th September, 1882.

Character assigned 100 A 2.82

Leahurst Marston
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
Reg. Book. (No. of Visits)
Tonnage { Net Built at When built
Gross
Under Dk. By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18