

ANNUAL SURVEYS.

41818

No. 52 Survey held at London Date, first Survey Sept. 14 Last Survey Sept 21 1882
 (Received at London Tuesday, 26th September)
 No. in Reg. Book. on the London & North Western Railway of London Master Pomroy
 Tonnage { Net 1380 Built at Glasgow When built 1871 Month. 11
 { Gross 2147
 { Under Dk. 2095 By whom built H. Napier & Sons Owners Shaw, Burby & Co
 Port belonging to London Destined Voyage Alago
 If Surveyed Afloat or in Dry Dock London and West India Dock
 (State Name of Dock.)

Last Survey, No. 41289 Port of London Classed 100 A.1
 Present Condition of the Decks good Treenails short good 28 fms 2.80 2.82
 Waterways put in do Breasthooks and Stenson do
 Comings good Transoms, Pointers, and Crutches do Windlass and Capstan good
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings good Pumps do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Boats do
 Planksheers none Keelsons good Masts, Yards, &c. do
 Sheerstrakes put in Clamps and Shelves put in good Condition, how ascertained from deck
 Topsides put in Ceiling good Sails complete
 Wales put in Rudder do Anchors, No. of 3 1/2 1 0 2 1/2
 Plank (Bottom) and Counter put in Copper or Y.M. do When put on do Cables not changed
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 Standing and Running Rigging good

General Observations, Opinion as to Class, &c. This vessel was docked, the bottom cleaned and repainted. Rudder lifted and painted. Sails luffed and spars cleaned. Being in good and efficient condition this vessel is eligible in my opinion to remain as classed.

Committee's Minute Tuesday, 10th October, 1882
 Character assigned 100 A.1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 (No. of Visits _____)
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____
 { Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
 (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 Standing and Running Rigging _____
 General Observations, Opinion as to Class, &c. _____
 Caulking of Bottom, Deck, & Waterways _____
 Hawfers and Warps _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery) (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.) (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.) (Insert Character precisely as in Register Book.)

