

ANNUAL SURVEYS.

41831

No. Survey held at London Date, first Survey 14th Sep^r Last Survey 30th Sept^r 1882
 No. in Reg. Book. 668 on the Barque "Christine" Master A. Platon
 Tonnage 386 Built at Southwick When built 1863 Month 9th
 Gross 386 By whom built Mills Owners Hankey & Co
 Under Dk. 367 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock In the Nelson Dry Dock.
 (State Name of Dock.)

Last Survey, No. 39426 Port of London

Present Condition of the			Classed	13	Character in Register Book.	A.1.
Decks	<u>good</u>	Treenails	<u>good</u>			
Waterways	<u>D^e</u>	Breasthooks and Stemson	<u>D^e</u>			
Comings	<u>D^e</u>	Transoms, Pointers, and Crutches	<u>D^e</u>			
Upper Deck Beams & Fastenings	<u>D^e</u>	Timbers of the Frame at the Openings	<u>D^e</u>			
Lower Deck Beams & Fastenings	<u>D^e</u>	Ditto ditto at other places	<u>D^e</u>			
Planksheers	<u>D^e</u>	Keelsons	<u>D^e</u>			
Sheerstrakes	<u>D^e</u>	Clamps and Shelves	<u>D^e</u>			
Topsides	<u>D^e</u>	Ceiling	<u>D^e</u>			
Wales	<u>D^e</u>	Rudder	<u>D^e</u>			
Plank (Bottom) and Counter	<u>D^e</u>	Copper or Y.M.	<u>good</u>	When put on	<u>7.80</u>	
Engine Room Skylights	<u>Coal Bunkers, Openings, Lids, &c.</u>	Scuppers	<u>good</u>	Cargo and Main Hatchways	<u>good</u>	Hatches
General Observations, Opinion as to Class, &c.	<u>This vessel is stated to have grounded in June last. The bottom has now been examined. Found the yellow metal on the port side abraded but not cut and the yellow metal sheathing free from wrinkling. Tested the caulking on removal of some of the bruised metal and also further aft and found it satisfactory. On examination of inside also found her free from damage. This vessel is in good and efficient condition & eligible in our opinion to remain as classed.</u>					

Committee's Minute Friday, 15th October, 1882.
 Character assigned Good
 Surveyor to Lloyd's Register of British and Foreign Shipping, J. H. Truscott, M.L.C. Davey
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built Year. Month.
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the					
Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors, No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper or Y.M.	When put on	Standing and Running Rigging	
Engine Room Skylights	Coal Bunkers, Openings, Lids, &c.	Scuppers		Cargo and Main Hatchways	Hatches
General Observations, Opinion as to Class, &c.					

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping,
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery...)

(Form No. 3 for Annual Survey, when there are no repairs. The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

LON 669-0132