

# ANNUAL SURVEYS.

No. 41849 Survey held at London Date, first Survey 11 Oct Last Survey 14 Oct 1882  
 No. in Reg. Book. 197 on the BK Firth of Forth Master R Campbell  
 Tonnage Net 830 Built at Dumbach When built 1875 Month 10  
 Gross 867 Under Dk. 812 By whom built Mr Kellar Owners J Spence & Co  
 Port belonging to Glasgow Destined Voyage Littleton  
 If Surveyed Afloat or in Dry Dock Blackwall Point Dr & afloat  
 (State Name of Dock.)

Last Survey, No. 5546 Port of GL  
 Present Condition of the  
 Decks good Treenails Rivets good  
 Waterways 11 Breasthooks and Stemon 11  
 Comings 11 Transoms, Pointers, and Crutches 11  
 Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11  
 Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11  
 Planksheers 11 Keelsons 11  
 Sheerstrakes 11 Clamps and Shelves 11  
 Topsides 11 Ceiling 11  
 Wales 11 Rudder 11  
 Plank (Bottom) and Counter 11 Copper or Y.M. coated When put on now  
 Engine Room Skylights 11 Coal Bunkers, Openings, Lids, &c. 11 Scuppers good Cargo and Main Hatchways good Hatches 11  
 General Observations, Opinion as to Class, &c. Bottom & coated  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 20th October, 1882.  
 Character assigned 100A  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 528 Survey held at London Date, first Survey 1 Sept Last Survey 16 Oct 1882  
 No. in Reg. Book. 528 on the S Roslin Castle Master Guthrie  
 Tonnage Net 1170 Built at Glasgow When built 1863 Month 7  
 Gross 1170 Under Dk. 1085 By whom built R Napier & Co Owners S Currie & Co  
 Port belonging to Liverpool Destined Voyage Australia?  
 If Surveyed Afloat or in Dry Dock Greens by BK  
 (State Name of Dock.)

Last Survey, No. 28315 Port of Liv  
 Present Condition of the  
 Decks good Treenails Rivets good  
 Waterways 11 Breasthooks and Stemon 11  
 Comings 11 Transoms, Pointers, and Crutches 11  
 Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11  
 Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11  
 Planksheers 11 Keelsons 11  
 Sheerstrakes 11 Clamps and Shelves 11  
 Topsides 11 Ceiling 11  
 Wales 11 Rudder 11  
 Plank (Bottom) and Counter 11 Copper or Y.M. coated When put on now  
 Engine Room Skylights 11 Coal Bunkers, Openings, Lids, &c. 11 Scuppers good Cargo and Main Hatchways good Hatches 11  
 General Observations, Opinion as to Class, &c. Bottom & coated  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 20th October, 1882.  
 Character assigned 100A  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18