

ANNUAL SURVEYS.

41864

No. _____ Survey held at London Date, first Survey 13th Oct Last Survey 14th Oct 1882
(Received at London Office, 25/10/82)

No. in Reg. Book. 275 on the Iron Ship "Carnarvon Castle" Master J. Blackmore.
(No. of Visits 2)

Tonnage 1200 Net 1200 Built at Glasgow When built 1867 Year. Month.
1165 Gross Under Dk. By whom built Barclay, Curle & Co Owners D. Currie & Co

Port belonging to London Destined Voyage Adelaide.
 If Surveyed Afloat or in Dry Dock In Green's Lower Dry Dock.
(State Name of Dock.)

Last Survey, No. 41095 Port of Lon

Present Condition of the			Classed	Years assigned.	Character in Register Book.
Decks	<u>good</u>	Treenails	<u>S.L. Lon. N-3-79.</u>	<u>1, 82</u>	<u>*A.1</u>
Waterways	<u>D^o</u>	Rivets			
Comings	<u>D^o</u>	Breasthooks and Stemson			
Upper Deck Beams & Fastenings	<u>D^o</u>	Transoms, Pointers, and Crutches			
Lower Deck Beams & Fastenings	<u>D^o</u>	Timbers of the Frame at the Openings			
Planksheers	<u>D^o</u>	Ditto ditto at other places			
Sheerstrakes	<u>D^o</u>	Keelsons			
Topsides	<u>D^o</u>	Clamps and Shelves			
Wales	<u>D^o</u>	Ceiling			
Plank (Bottom) and Counter	<u>D^o</u>	Rudder			
Engine Room Skylights		Copper or Y.M. When put on			
Coal Bunkers, Openings, Lids, &c.		Caulking of Bottom, Deck, & Waterways			
Scuppers	<u>good.</u>				
Cargo and Main Hatchways	<u>good</u>				
Hatches	<u>good.</u>				

General Observations, Opinion as to Class, &c.
The bottom has been examined and coated. Vessel surveyed with ballast in the hold amidships. She appears to be in good and efficient condition & eligible to remain as classed.

Committee's Minute Friday, 27th October, 1882.
 Character assigned JRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
(No. of Visits _____)

No. in Reg. Book. _____ on the _____ Master _____
Year. Month.

Tonnage Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____

Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____

Present Condition of the			Classed	Years assigned.	Character in Register Book.
Decks		Treenails			
Waterways		Breasthooks and Stemson			
Comings		Transoms, Pointers, and Crutches			
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			
Lower Deck Beams & Fastenings		Ditto ditto at other places			
Planksheers		Keelsons			
Sheerstrakes		Clamps and Shelves			
Topsides		Ceiling			
Wales		Rudder			
Plank (Bottom) and Counter		Copper or Y.M. When put on			
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways			
Coal Bunkers, Openings, Lids, &c.					
Scuppers					
Cargo and Main Hatchways					
Hatches					

General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82. (If a Steam Ship, state if a Report is also sent on the Machinery. The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book. LON 669-0167

