

ANNUAL SURVEYS.

41876

(Received at London Office, Friday, 13th October, 1882.)

No. Survey held at London Date, first Survey 7 Oct Last Survey 7 Oct 1882

No. in on the Reg. Book. 4 on the SS Gorkha Master Sharp (No. of Visits)
 Tonnage { Net 2660 Built at Sumbarton When built 1882 Month. 3
 { Gross 4104
 { Under Dk. 2612 By whom built W Benny & Bros Owners Brit Ind St Nav Co
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Albert Dry Dock (State Name of Dock.)

Last Survey, No. 5721 Port of Gls Classed 100A 1.5.82

Present Condition of the Decks <u>good</u>	Treenails <u>Rivets</u>	<u>good</u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	<u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	<u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	<u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	<u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	<u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	<u> </u>
Topsides <u> </u>	Ceiling <u> </u>	<u> </u>
Wales <u> </u>	Rudder <u> </u>	<u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u>bruted</u> When put on <u>new</u>	<u> </u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	<u> </u>
Coal Bunkers, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
Hatches <u> </u>		

General Observations, Opinion as to Class, &c. Bottom bruted
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, 31st October, 1882. Senhouse Martindale
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Reg. Book. on the Master (No. of Visits)
 Tonnage { Net Built at When built Year. Month.
 { Gross
 { Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed 18

Present Condition of the Decks <u> </u>	Treenails <u> </u>	<u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	<u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	<u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	<u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	<u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	<u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	<u> </u>
Topsides <u> </u>	Ceiling <u> </u>	<u> </u>
Wales <u> </u>	Rudder <u> </u>	<u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	<u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	<u> </u>
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Cargo and Main Hatchways <u> </u>
Hatches <u> </u>		

General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18



The Surveyors are requested not to write on or below the space for Committee's Minute. (If a Steam Ship.)

Insert Character precisely as in Register Book.

LOND 69-0182