

ANNUAL SURVEYS.

41883

(Received at London Office, 25/10/82)
Date, first Survey 12th Oct^r Last Survey 14th Oct^r 1882

No. 1297 Survey held at London No. in Reg. Book 1297 on the "Iron Steamer 'Courland'" Master W. Warden (No. of Visits 2)
 Tonnage Net 803 Gross 1241 Under Dk. 1221 Built at Glasgow When built 1872 Month 7th
 By whom built R. Napier & Sons Owners Leith, Hull & Hamb. Ste. Sh. Co.
 Port belonging to London Destined Voyage not known
 If Surveyed Afloat or in Dry Dock In Green's Middle Dry Dock (State Name of Dock.)

Last Survey, No. 41039 Port of London Classed 100 A.1. Years assigned 10, 81. Character in Register Book S.L. Lon. N^o 2-80
 Present Condition of the Decks good Treenails good Rivets good
 Waterways D^o Breasthooks and Stenson D^o
 Comings D^o Transoms, Pointers, and Crutches D^o Windlass and Capstan good
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o Pumps D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o Boats D^o
 Planksheers D^o Keelsons D^o Masts, Yards, &c. D^o
 Sheerstrakes D^o Clamps and Shelves D^o Condition, how ascertained from the deck
 Topsides D^o Ceiling D^o Sails good
 Wales D^o Rudder D^o Anchors, No. of 4 B. 1 S. 2 K.
 Plank (Bottom) and Counter D^o Copper or Y.M. When put on Cables complete
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated. This vessel appears to be in good and efficient condition and eligible to remain as classed.

Committee's Minute Tuesday, 31st October, 1882 Surveyor to Lloyd's Register of British and Foreign Shipping. J. H. Truscott.
 Character assigned 100 A.1 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 (No. of Visits _____)
 No. in Reg. Book _____ on the _____ Master _____
 Year _____ Month _____
 Tonnage Net _____ Gross _____ Under Dk. _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)
 Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book _____
 Present Condition of the Decks _____ Treenails _____ Rivets _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____ Windlass and Capstan _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Pumps _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Boats _____
 Planksheers _____ Keelsons _____ Masts, Yards, &c. _____
 Sheerstrakes _____ Clamps and Shelves _____ Condition, how ascertained _____
 Topsides _____ Ceiling _____ Sails _____
 Wales _____ Rudder _____ Anchors, No. of _____
 Plank (Bottom) and Counter _____ Copper or Y.M. When put on Cables _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Character assigned _____ Certificate (if required, to be sent as per margin) Paid _____

(If a Steam Ship, state if a Report is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute...)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 LON 669-0188

