

## ANNUAL SURVEYS.

41908

No. 529 Survey held at London Date, first Survey Oct 28 Last Survey Nov 1 18 82  
(Received at London Office, Friday, 3rd November, 1882)  
No. in Reg. Book. on the Steamer "Charles Lapper" Master Walker  
Tonnage { Net 449 Built at Newcastle When built 1864 Year. 6 Month. 6  
Gross 761  
Under Dk. 706 By whom built Palmer Bros & Co Owners Harris and Brown  
Port belonging to London Destined Voyage London  
If Surveyed Afloat or in Dry Dock London dry dock (State Name of Dock.)

Last Survey, No. 1586 Port of New Classed 85 A.1  
Present Condition of the Decks good Treenails fresh good A. S. Shell 3.82 2.82  
Waterways do Breasthooks and Stemson do  
Comings do Transoms, Pointers, and Crutches do  
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings good  
Lower Deck Beams & Fastenings do Ditto ditto at other places do  
Planksheers new Keelsons good  
Sheerstrakes good Clamps and Shelves strong do  
Topsides do Ceiling good  
Wales do Rudder do  
Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓  
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
General Observations, Opinion as to Class, &c. This vessel was docked, the bottom cleaned and coated, the Rudder lifted and brass bushed. Being now in good and efficient condition this vessel is eligible to remain as classed.

Committee's Minute Friday, 10th November, 1882.Character assigned TRW 85 A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18No. \* Survey held at \* Date, first Survey \* Last Survey 18

No. in Reg. Book. on the \* Master \*  
Tonnage { Net \* Built at \* When built \* Year. \* Month. \*  
Gross \*  
Under Dk. \* By whom built \* Owners \*  
Port belonging to \* Destined Voyage \*  
If Surveyed Afloat or in Dry Dock \* (State Name of Dock.)

Last Survey, No. \* Port of \* Classed \*  
Present Condition of the Decks \* Treenails \*  
Waterways \* Breasthooks and Stemson \*  
Comings \* Transoms, Pointers, and Crutches \*  
Upper Deck Beams & Fastenings \* Timbers of the Frame at the Openings \*  
Lower Deck Beams & Fastenings \* Ditto ditto at other places \*  
Planksheers \* Keelsons \*  
Sheerstrakes \* Clamps and Shelves \*  
Topsides \* Ceiling \*  
Wales \* Rudder \*  
Plank (Bottom) and Counter \* Copper or Y.M. \* When put on \*  
Engine Room Skylights \* Coal Bunkers, Openings, Lids, &c. \* Scuppers \* Cargo and Main Hatchways \* Hatches \*  
General Observations, Opinion as to Class, &c. \*

Committee's Minute 18Character assigned \*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-20/4/82.) (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Machinery.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

LON 669-0218