

ANNUAL SURVEYS.

41922

No. 914 Survey held at London Date, first Survey 1st Novr Last Survey 11th Novr 1882
 No. in Reg. Book. 914 on the Iron Bk. "Star of Denmark" Master J. Legg
 Tonnage { Net 998 Built at Belfast When built 1863 Month 6
 Gross 998 By whom built Harland & Wolff Owners J. Corry & Co
 Under Dk. 971 Port belonging to Belfast Destined Voyage Melbourne.
 If Surveyed Afloat or in Dry Dock In Green's Middle Dry Dock
 (State Name of Dock.)

Last Survey, No. 41209 Port of London Classed *A.1
 Present Condition of the
 Decks good Treennails good Rivets good S.L. Lon. N° 3-76 1,82
 Waterways do Breasthooks and Stemson do S.L. Lon. N° 1-81.
 Comings do Transoms, Pointers, and Crutches do Windlass and Capstan good
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Boats do
 Planksheers do Keelsons do Masts, Yards, &c. do
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from the deck
 Topsides do Ceiling do Sails good
 Wales do Rudder do Anchors, No. of 3 B. 15. 2 K.
 Plank (Bottom) and Counter do Copper or Y.M. When put on Cables complete
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
The bottom has been examined and coated. The jibboom renewed.
Vessel surveyed with part outward cargo in hold.
The freeboard assigned by the Committee for this vessel viz: 4-6 in salt water and 4-1 1/2
in fresh water (see Committee's Minute dated 9th Novr/82) has now been marked on the vessel's
sides. This vessel is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, 11th November 1882
 Character assigned *A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage { Net Built at When built Year. Month.
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

 Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.)
 (If a Steam Ship, state if a Report is also sent on the Machinery)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 LON 669-0234

