

# ANNUAL SURVEYS.

41939

No. 919 Survey held at London Date, first Survey October 26<sup>th</sup> Last Survey November 9<sup>th</sup> 1882  
 No. in Reg. Book. 919 on the Iron Ship "Star of Germany" Master J. H. Mills  
 Tonnage 1284 Built at Belfast When built 1872 - 3  
 Gross 1337 Under Dk. 1256 By whom built Harland & Wolff Owners J. Corry & Co.  
 Port belonging to Belfast Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Canal dry Dock and Afloat  
 Last Survey, No. 41262 Port of Low Classed 100 A 1

Present Condition of the  
 Decks good Treennails Rivets good S.S. Don No 2-80 2, 82  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shells Stringers "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1872  
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways good  
 Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has now been placed in dry dock the bottom examined and recoated with Paint. It is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

Tuesday, 21<sup>st</sup> November, 18 82.

Character assigned

100 A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 283 Survey held at London Date, first Survey November 3<sup>rd</sup> Last Survey November 7<sup>th</sup> 1882  
 No. in Reg. Book. 283 on the Iron Ship "Benau" Master Burns  
 Tonnage 1338 Built at Glasgow When built 1875 - 4  
 Gross 1416 Under Dk. 1291 By whom built Barclay Currie & Co. Owners W. Thompson & Co.  
 Port belonging to Leith Destined Voyage Wtago  
 If Surveyed Afloat or in Dry Dock Canal dry Dock and Afloat  
 Last Survey, No. 41441 Port of Leith Classed 100 A 1

Present Condition of the  
 Decks good Treennails Rivets good S.S. Don No 1-79 12, 81  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shells "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1875  
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways good  
 Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has now been placed in dry dock the bottom examined and recoated with Paint, it is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

Tuesday, 21<sup>st</sup> November, 18 82.

Character assigned

100 A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)

(If a Steam Ship, state if a Report is also sent on the Machinery)

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

4520-6990254