

ANNUAL SURVEYS.

23/11/82
No. 208 on the SS Viking
Survey held at London Date, first Survey 20 Nov Last Survey 23 Nov 1882
Master R. J. J. J.
Tonnage Net 1686 Gross 2588 Under Dk. 1753 Built at Glasgow When built 1874 Month 6
By whom built Aitken & Co Owners W. Ross & Co
Port belonging to Glasgow Destined Voyage River Plate
If Surveyed Afloat or in Dry Dock Afloat Victoria St Port Cairn in

Last Survey, No. 12925 Port of Sld
Present Condition of the Decks Good Treenails Rivets
Waterways Good Breasthooks and Stemson Good
Comings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shelves Good
Topsides Good Ceiling Good
Wales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. When put on Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. She is now in an efficient & eligible condition to remain as classed and on her return from the present voyage to undergo SS M2 survey. The 30 fathoms of chain cable put on board last year has now been examined & testing certificate produced 30 fathoms chain cable 1 1/4 tested to 6 1/2 tons breaking strain 9 1/2 tons net weight 10 tons - dated Jan 24/81 signed S. J. Lewis.
Committee's Minute Tuesday, 28th November, 1882
Character assigned 100 A-12.81
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Net Built at When built
Gross Built at When built
Under Dk. By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock (State Name of Dock.)
Last Survey, No. Port of Classed
Present Condition of the Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.
Committee's Minute 18
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18