

ANNUAL SURVEYS.

42000

No. 555 Survey held at London Date, first Survey 2nd Dec Last Survey 4th Dec 1882
 (Received at London Office, 9.12.82)
 No. in Reg. Book. 555 on the S Loch Nefs Master M. Mathieson
 Tonnage 1120 Net 1248 Gross 1121 Under Dk. 1121 Built at Glasgow When built 1867
 By whom built Burday & Co Owners Glasgow Ship Co
 Port belonging to Glasgow Destined Voyage Glasgow
 If Surveyed Afloat or in Dry Dock Blackburne & Co
 (State Name of Dock.)

Last Survey, No. 5646 Port of Glasgow
 Present Condition of the
 Decks Good Treenails Put in Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom painted
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Tuesday, 12th December, 1882.
 Character assigned A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 555 Survey held at London Date, first Survey 2nd Dec Last Survey 4th Dec 1882
 (No. of Visits 1)
 No. in Reg. Book. 555 on the S Loch Nefs Master M. Mathieson
 Tonnage 1120 Net 1248 Gross 1121 Under Dk. 1121 Built at Glasgow When built 1867
 By whom built Burday & Co Owners Glasgow Ship Co
 Port belonging to Glasgow Destined Voyage Glasgow
 If Surveyed Afloat or in Dry Dock Blackburne & Co
 (State Name of Dock.)
 Last Survey, No. 5646 Port of Glasgow Classed A1
 Present Condition of the
 Decks Good Treenails Put in
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom painted
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute 18
 Character assigned A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18