

ANNUAL SURVEYS.

42006

No. _____ Survey held at London Date, first Survey 13 Nov Last Survey 18th Nov 1882
(Received at London Office, 22-11-82)
(No. of Visits 4)

No. in on the Reg. Book. 191 on the SS Manora Master _____
 Net 2120 Built at Lumbarton When built 1878 Year. _____ Month. 3
 Tonnage Gross 3242 By whom built W Denny & Co Owners J Macneil & P Denny
 Under Dk. 3166 Port belonging to Glasgow Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Albert Quay St & Vapour
(State Name of Dock.)

Last Survey, No. 416266 Port of Leam Classed 100 A. 6. 82
Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson	"	Windlass and Capstan <u>Good</u>
Comings	"	Transoms, Pointers, and Crutches	"	Pumps <u>"</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats <u>"</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c. <u>"</u>
Planksheers	"	Keelsons	"	Condition, how ascertained <u>From St</u>
Sheerstrakes	"	Clamps and Shelves	"	Sails <u>Good</u>
Topsides	"	Ceiling	"	Anchors, No. of <u>3 Pro St & Redys</u>
Wales	"	Rudder	"	Cables <u>Paul on the</u> <u>Good</u>
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Boiled</u> When put on <u>Now</u>	"	Hawsers and Warps <u>"</u>
Engine Room Skylights <u>Good</u>		Caulking of Bottom, Deck, & Waterways <u>Good</u>	"	Standing and Running Rigging <u>"</u>
Coal Bunkers, Openings, Lids, &c. <u>Good</u>		Scuppers <u>Good</u>		Cargo and Main Hatchways <u>Good</u>
Hatches <u>"</u>				

General Observations, Opinion as to Class, &c. The fore hold & after ditto were surveyed last June for SS No 1 as per London Report 41626. Attended, as agreed upon with Captain Brown the Manager, and the Charterers had their hands putting cargo in the main hold as fast as the Bullard was taken out, both parties working at the same time in one Hatchway. She is in good condition & respectfully recommend her to remain as classed. I Captain states she will be prepared to complete the Survey on her return from the present voyage.

Committee's Minute Tuesday, 12th December, 1882. Senhouse Martindeale
 Character assigned JRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
(No. of Visits _____)

No. in on the Reg. Book. _____ on the _____ Master _____
 Year. _____ Month. _____
 Tonnage Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Destined Voyage _____
 Port belonging to _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks		Treenails		
Waterways		Breasthooks and Stemson		Windlass and Capstan
Comings		Transoms, Pointers, and Crutches		Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Boats
Lower Deck Beams & Fastenings		Ditto ditto at other places		Masts, Yards, &c.
Planksheers		Keelsons		Condition, how ascertained
Sheerstrakes		Clamps and Shelves		Sails
Topsides		Ceiling		Anchors, No. of
Wales		Rudder		Cables
Plank (Bottom) and Counter		Copper or Y.M. _____ When put on _____		Hawsers and Warps
Engine Room Skylights _____		Caulking of Bottom, Deck, & Waterways _____		Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c. _____		Scuppers _____		Cargo and Main Hatchways _____
Hatches _____				

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.



LON 669-0339