

# ANNUAL SURVEYS.

42008

No. 168 Survey held at London Date, first Survey 15<sup>th</sup> Nov Last Survey 30 Nov 1882  
 (Received at London Office, 2. 12. 82)  
 No. in Reg. Book. on the S S Thames Master James  
 (No. of Visits \_\_\_\_\_)  
 Tonnage Net 1057 Built at Gumbarton When built 1871 Month. 3  
Gross 1687 By whom built A Mc Millan Owners Temperleys Carter & Burke  
Under Dk. 1657 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Victoria St  
 (State Name of Dock.)

Last Survey, No. 40138 Port of London Classed 100 A Years assigned. 5.82 Character in Register Book.

Present Condition of the Decks <u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>	Condition, how ascertained <u>from Stk</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>	Sails <u>good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>	Anchor, No. of <u>3 No. St &amp; Reddy</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>	Cables <u>Port on Stk</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. _____ When put on _____	<u>"</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	<u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunkers, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	<u>good</u>	Hatches <u>"</u>

General Observations, Opinion as to Class, &c. This vessel lost a Bower & 45 fathoms of Main Cable last Voyage in the River St Lawrence and were recovered after she left there & were replaced with others on her arrival. She has been out there again and her own Anchor & 45 fathoms of Chain have been placed on board. She is now in an efficient state and eligible to remain as classed

Committee's Minute Tuesday, 12th December, 1882 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Character assigned 100 A Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 (No. of Visits \_\_\_\_\_)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Under Dk. \_\_\_\_\_ Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
 (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book.

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchor, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)  
 LON 669-0341

