

ANNUAL SURVEYS.

42077

No.

Survey held at London

Date, first Survey 14 Dec

Last Survey 28 Dec

1882

No. in Reg. Book.

on the SS Sunnol Castle

Master

Harrison

488

Tonnage { Net 1784
Gross 2811
Under Dk. 2737

Built at Glasgow

When built 1875

Month. 11

By whom built R Napier & Sons

Owners J Burrie & Co

Port belonging to

London

Destined Voyage

Cape

If Surveyed Afloat or in Dry Dock

Thames Iron Works Dry Dock

Last Survey, No.

41038

Port of

London

Classed

100A1 1181
SS Lon No 180

Present Condition of the

Decks

Good

Treenails Rivets

Good

Waterways

"

Breasthooks and Stemson

"

Comings

"

Transoms, Pointers, and Crutches

"

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the Openings

"

Lower Deck Beams & Fastenings

"

Ditto ditto at other places

"

Planksheers

"

Keelsons

"

Sheerstrakes

"

Clamps and Shelves

"

Topsides

"

Ceiling

"

Wales

"

Rudder

"

Plank (Bottom) and Counter

"

Copper or Y.M. Coated

When put on new

Caulking of

Bottom, Deck, & Waterways

Good

Engine Room Skylights

Good

Coal Bunkers, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

"

General Observations, Opinion as to Class, &c.

Bottom & coated

She is now in an efficient state and eligible to remain as classed

Brown Anchor supplied & Testing Certificate Produced 28 Dec 1882

40-1-20 tested to 36 tons 2 test Chester Proving House dated 15 Dec 1882 signed Andrew S Jack

Committee's Minute

Friday, 5th January, 1883.

Leithhouse Martindale

Character assigned

100A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid 18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in Reg. Book.

on the

Master

(No. of Visits)

Year.

Month.

Tonnage { Net
Gross
Under Dk.

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock.)

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Treenails

Waterways

Breasthooks and Stemson

Windlass and Capstan

Comings

Transoms, Pointers, and Crutches

Pumps

Deck Beams & Fastenings

Timbers of the Frame at the Openings

Boats

Deck Beams & Fastenings

Ditto ditto at other places

Masts, Yards, &c.

sheers

Keelsons

Condition, how ascertained

trakes

Clamps and Shelves

Sails

les

Ceiling

Anchors, No. of

Rudder

Cables

(Bottom) and Counter

Copper or Y.M. When put on

Hawsers and Warps

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute


18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid 18



© 2021

Lloyd's Register Foundation

