

REPORT of SURVEY for REPAIRS, &c.

No. in Survey held at London Date, first Survey 30th Dec 1872 Last Survey 1st January 1883
 eg. Book. 121 on the Brigantine "Olive Branch" Master F. Ridge
 Tonnage under Tonnage Deck 178 Built at Peterhead When built 1872
 Ditto of Spar Deck, or Awning Deck Owners H. Good Port belonging to London
 Ditto of Poop Ditto of Raised Qr. Dk. Residence Bridport
 Ditto of Houses on Deck By whom built Carnegie Destined Voyage Newcastle, thence to Bridport
 Ditto of Forecastle Gross Tonnage 191 If Surveyed Afloat or in Dry Dock In Bull Head Dry Dock
 Crew Space, as per Rule Register Tonnage, cut on Beam 180 (State Name of Dock)
 Engine Room Reg. Tons as S'mer, cut on Bm.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Last Survey, No. 3403 Port Adm Cont. Pet. July 81 - 16 4, 82.
 REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated.
 Society's Load Line (if assigned) as painted on Ship
 Society's Freeboard (if assigned) as painted on Ship

Change of Owners.

This vessel has been placed in dry dock and the bottom sighted. About thirty feet of the false keel renewed of American elm.
 Vessel surveyed with ballast in the hold, fore and aft.

| | | | | | |
|--|------|--|------|--|----------------|
| Present Condition of the | | | | | |
| Decks | good | Treenails | good | Windlass and ^{winch} Capstan | good |
| Walls | ge | Breasthooks and Stemson | ge | Pumps | ge |
| Comings | ge | Transoms, Pointers, and Crutches | ge | Boats | ge |
| Upper Deck Beams & Fastenings | ge | Timbers of the Frame at the openings | ge | Masts, Yards, &c. | ge |
| Lower Deck Beams & Fastenings | | Ditto Ditto at other places | ge | Condition, how ascertained from the deck | |
| Planksheers | ge | Keelsons | ge | Sails | good |
| Strakes | ge | Clamps and Shelves | ge | Anchor No. of | 3 B. 1 S. 1 K. |
| Topsides | ge | Ceiling | ge | Cables | complete |
| Wales | ge | Rudder | ge | Hawsers and Warps | good |
| Plank (Bottom) and Counter | ge | Copper ^{Fe} (if Y.M.) good When put on 4, 82. (State if on Felt.) | | Standing & Running Rigging | ge |
| Engine Room Skylights | | Cement (if Iron Ship) | | Cargo and Main Hatchways | good |
| Coal Bunker, Openings, Lids, &c. | | Caulking of Bottom, Deck, & Waterways | good | Hatches | good |
| Scuppers | good | | | | |

General Observations, Opinion as to Class, &c.
 This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

The Amount of Entry Fee ... £ : 10 : received by me, }
 Special ... £ : : } Jan 1883 }
 Certificate (if required) } £ : 2 : 6 }
 to be sent as per margin... }
 (Travelling Expenses, if any, £)
 Committee's Minute
 Character assigned
 Tuesday 16th January 1883
 J. H. Truscott.
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021
 Lloyd's Register
 Foundation