

REPORT of SURVEY for REPAIRS, &c.

SS No. 1

42112

No. in Survey held at London Date, first Survey 5 Jan'y Last Survey 11 Jan'y 1883
 Reg. Book. 5 on the SS Oakdale (No. of Visits) Master H. F. Cabrne
 TONNAGE under Tonnage Deck 1094 Built at Hartlepool When built 1878 YEAR. MONTH.
 Ditto of Spar Deck, or Awning Deck Owners Steel Young & Co. Port belonging to London
 Ditto of Poop Residence E. Mithey
 Ditto of Raised Qr. Dk. By whom built E. Mithey Destined Voyage Swansea
 Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock Pontoon Victoria St
 Ditto of Forecastle (State Name of Dock)
 Gross Tonnage 1408
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St'mer, cut on Bm. 887
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 41170 Port London Classed 100A1-2.82
 REPAIRS, OR EXAMINATION AS PER RULE Special Survey No. 1
 Cause of Repairs to be clearly stated.

At present all the ceiling taken off the top of double bottom & the timbers lifted at the bilges, & the Man hole doors removed, examined and found good and the cement adhering firmly to the iron. The top of double bottom plates coated with tar and lime which is a very good preservative for iron. The Wood ceiling replaced, Man hole doors secured, and the double bottom tested to light mark. The Rudder bushed & the outside coated.

Present Condition of the

Decks	Good	Greenails	Nails	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	Examined
Planksheers	"	Keelsons		"	Sails	Good
Sheerstrakes	"	Clamps and Shelves		"	Anchors No. of 3 Bcs SH & Hedges	
Topsides	"	Ceiling		"	Cables Part on SH	Good
Wales	"	Rudder Bushed		"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or P.M.) Coated When put on	Now		Standing & Running Rigging	"
Engine Room Skylights	Good	Caulking of			Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good		Hatches	"
General Observations, Opinion as to Class, &c.		Scuppers	Good			

General Observations, Opinion as to Class, &c.

She is now in an efficient state and eligible to remain as classed, and to be marked SS London No 1-1883.

Senhouse Martindale

The Amount of Entry Fee ... £ : : : received by me, }
 18/1/83 Special ... £ 4 : 4 : } 30th Jan 1883

Certificate (if required) }
 be sent as per margin... } £ - : 5 : -

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Friday, 10th January 1883

1001-1



© 2021

Lloyd's Register Foundation

240669-0472