

ANNUAL SURVEYS.

No. 968 Survey held at London Date, first Survey 9 Jan Last Survey 10th Jan 1883
 No. in on the SS Monarch Master Thompson
 Reg. Book. 968 Net 1522 Built at Middlesbo When built 1878 Year. 7 Month.
 Tonnage Gross 2866 Under Dk. 2055 By whom built R Dixon & Co Owners Macintyre
 Port belonging to Newcastle Destined Voyage not fixed when in bond
 If Surveyed Afloat or in Dry Dock Blackwall Point by SW
 (State Name of Dock.)

Last Survey, No. 385 Port of N. Y. P. Classed - Years assigned. 100A1 Character in Register Book. 11-82

Present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u>	Good
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	"
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	"
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	"
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	"
Planksheers <u>"</u>	Keelsons <u>"</u>	"
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	"
Topsides <u>"</u>	Ceiling <u>"</u>	"
Wales <u>"</u>	Rudder <u>"</u>	"
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>now</u>	"
Engine Room Skylights <u>"</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	"
Coal Bunkers, Openings, Lids, &c. <u>"</u>	Scuppers <u>Good</u>	"
General Observations, Opinion as to Class, &c. <u>"</u>	Cargo and Main Hatchways <u>Good</u>	"
	Hatches <u>"</u>	"

Bottom & coated & new paint supplied. She is now in an efficient state and eligible to remain as classed. Thomas Bengtson has reported this defect & recommended her to go into Dry Dock to see her bottom. I have examined it & she was only shapen on planks.

Committee's Minute Friday, 19th January, 1883. Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the

Decks <u></u>	Treenails <u></u>	
Waterways <u></u>	Breasthooks and Stemson <u></u>	
Comings <u></u>	Transoms, Pointers, and Crutches <u></u>	
Upper Deck Beams & Fastenings <u></u>	Timbers of the Frame at the Openings <u></u>	
Lower Deck Beams & Fastenings <u></u>	Ditto ditto at other places <u></u>	
Planksheers <u></u>	Keelsons <u></u>	
Sheerstrakes <u></u>	Clamps and Shelves <u></u>	
Topsides <u></u>	Ceiling <u></u>	
Wales <u></u>	Rudder <u></u>	
Plank (Bottom) and Counter <u></u>	Copper or Y.M. <u></u> When put on <u></u>	
Engine Room Skylights <u></u>	Caulking of Bottom, Deck, & Waterways <u></u>	
Coal Bunkers, Openings, Lids, &c. <u></u>	Scuppers <u></u>	
General Observations, Opinion as to Class, &c. <u></u>	Cargo and Main Hatchways <u></u>	
	Hatches <u></u>	

Committee's Minute 18 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Memorandum

Last Survey, No.		Port of		Present Condition of the	
No.		No.		No.	
1		2		3	
2		3		4	
3		4		5	
4		5		6	
5		6		7	
6		7		8	
7		8		9	
8		9		10	
9		10		11	
10		11		12	
11		12		13	
12		13		14	
13		14		15	
14		15		16	
15		16		17	
16		17		18	
17		18		19	
18		19		20	
19		20		21	
20		21		22	
21		22		23	
22		23		24	
23		24		25	
24		25		26	
25		26		27	
26		27		28	
27		28		29	
28		29		30	
29		30		31	
30		31		32	
31		32		33	
32		33		34	
33		34		35	
34		35		36	
35		36		37	
36		37		38	
37		38		39	
38		39		40	
39		40		41	
40		41		42	
41		42		43	
42		43		44	
43		44		45	
44		45		46	
45		46		47	
46		47		48	
47		48		49	
48		49		50	
49		50		51	
50		51		52	
51		52		53	
52		53		54	
53		54		55	
54		55		56	
55		56		57	
56		57		58	
57		58		59	
58		59		60	
59		60		61	
60		61		62	
61		62		63	
62		63		64	
63		64		65	
64		65		66	
65		66		67	
66		67		68	
67		68		69	
68		69		70	
69		70		71	
70		71		72	
71		72		73	
72		73		74	
73		74		75	
74		75		76	
75		76		77	
76		77		78	
77		78		79	
78		79		80	
79		80		81	
80		81		82	
81		82		83	
82		83		84	
83		84		85	
84		85		86	
85		86		87	
86		87		88	
87		88		89	
88		89		90	
89		90		91	
90		91		92	
91		92		93	
92		93		94	
93		94		95	
94		95		96	
95		96		97	
96		97		98	
97		98		99	
98		99		100	