

# ANNUAL SURVEYS.

42119

No.          Survey held at London Date, first Survey 25 Nov/82 Last Survey 2 Jan/83 1883  
(Received at London Office, 4 Jan/83)  
No. in on the SS Garth Castle Master M P Webster  
Reg. Book.          (No. of Visits         )  
01 Tonnage { Net 2881 Built at Glasgow When built 1880 12 Month.  
Gross 3705  
Under Dk. 2537 By whom built J Elbert Owners S Currie & Co  
Port belonging to London Destined Voyage Cape  
If Surveyed Afloat or in Dry Dock Guano by Mr J Elbert  
(State Name of Dock.)

Last Survey, No. 41781 Port of London Classed 100 A 1 Years assigned. 100 A 1 Character in Register Book.           
Present Condition of the  
Decks Good Treennails Good Rivets Good  
Waterways Good Breasthooks and Stemson Good  
Comings Good Transoms, Pointers, and Crutches Good  
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
Planksheers Good Keelsons Good  
Sheerstrakes Good Clamps and Shelves Good  
Topsides Good Ceiling Good  
Wales Good Rudder Good  
Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on new  
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Bottom be covered.  
She is now in an efficient state  
and eligible to remain as classed.

Committee's Minute Friday, 19th January, 1883. Senhouse Martineau  
Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin)          Paid          18         

No.          Survey held at          Date, first Survey          Last Survey          18           
(No. of Visits         )  
No. in on the          Master           
Reg. Book.          (No. of Visits         )  
Tonnage { Net          Built at          When built           
Gross          By whom built          Owners           
Under Dk.           
Port belonging to          Destined Voyage           
If Surveyed Afloat or in Dry Dock           
(State Name of Dock.)

Last Survey, No.          Port of          Classed          Years assigned.          Character in Register Book.           
Present Condition of the  
Decks          Treennails           
Waterways          Breasthooks and Stemson           
Comings          Transoms, Pointers, and Crutches           
Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings           
Lower Deck Beams & Fastenings          Ditto ditto at other places           
Planksheers          Keelsons           
Sheerstrakes          Clamps and Shelves           
Topsides          Ceiling           
Wales          Rudder           
Plank (Bottom) and Counter          Copper or Y.M.          When put on           
Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches           
General Observations, Opinion as to Class, &c.         

Committee's Minute          18           
Character assigned          Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin)          Paid          18