

ANNUAL SURVEYS.

42122

No. 86 Survey held at London Date, first Survey 12 July (Received at London Office, 4.1.83) Last Survey 30 Dec 1882
 No. in Reg. Book. on the SS Taymouth Castle Master _____ (No. of Visits _____)
 Tonnage { Net 1172 Built at Glasgow When built 1877 Year. 3 Month. _____
 Gross 1827 By whom built Barday & Co Owners J Currie & Co
 Under Dk. 1780 Port belonging to London Destined Voyage Laid up
 If Surveyed Afloat or in Dry Dock Greens by M & Afloat (State Name of Dock.)



Last Survey, No. 41425 Port of Lon.
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches _____
 General Observations, Opinion as to Class, &c. The Chain Cables have been hauled from the locker & ranged for the Government Surveyors, & have been examined by me 300 fathoms in all. She is now in an efficient state and eligible to remain as classed, she has been laid up a long time & is now at a laid up getting
 Committee's Minute Friday, 19th January, 1883.
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. on the _____ Master _____ (No. of Visits _____)
 Tonnage { Net _____ Built at _____ When built _____ Year. _____ Month. _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)
 Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required, to be sent as per margin) Paid _____ 18 _____



Insert Character precisely as in Register Book.

LON669-0488