

REPORT of SURVEY for REPAIRS, &c.

42136

(Received at London Office, 12.1.83)

in Survey held at London Date, first Survey 12th Jan Last Survey 16th Jan 1883
 Book. 29 on the Iron S.S. "Petrarch" (No. of Visits) Master R. Lohu
 TONNAGE under Tonnage Deck 1444 YEAR. MONTH.
 Ditto of Spar Deck, or Awning Deck Built at S Shields When built 1877
 Ditto of Poop Owners M^r Andrew Ho Port belonging to London
 Ditto of Raised Qr. Dk. Residence
 Ditto of Houses on Deck By whom built Readhead Destined Voyage Hamburg
 Ditto of Forecastle Gross Tonnage 1693
 Crew Space, as per Rule If Surveyed Afloat or in Dry Dock Caster's dry Dock & Afloat
 Register Tonnage, cut on Beam (State Name of Dock) Years assigned. Character in Register Book.
 Engine Room Reg. Tons as St^rmer, cut on Bm. 1297
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Last Survey, No. 41018 Port Lon Classed 100A / 12.81
S.S. hoi - 81
 REPAIRS, OR EXAMINATION AS PER RULE Society's Load-Line (if assigned) as painted on Ship
 Cause of Repairs to be clearly stated. Society's Freeboard (if assigned) as painted on Ship

Bottom recoated. a few rivets renewed in After End of keel and lower part of Post
 30 fms 1 3/4" Chain Cable No 1545 Tests 56 1/8 + 77 1/8 Tons Low Walker
 Public machine 23rd June 1875 Robt Bunnell Supt? now supplied to make good deficiency

Present Condition of the	Good	Repairs	Good	Windlass and Capstan	Good
Decks	Good	Frenails	Good		
Waterways	--	Breasthooks and Stemson	--	Pumps	--
Comings	--	Transoms, Pointers, and Crutches	--	Boats <u>5 ho</u>	--
Upper Deck Beams & Fastenings	--	Timbers of the Frame at the openings	--	Masts, Yards, &c.	--
Lower Deck Beams & Fastenings	--	Ditto Ditto at other places	--	Condition, how ascertained <u>from Dk</u>	
Planksheers	--	Keelsons	--	Sails	<u>Good</u>
Sheerstrakes	--	Clamps and Shells	--	Anchor No. of <u>4 B. 1 S + 2 K</u>	
Topsides	--	Ceiling	--	Cables	<u>Good</u>
Wales	--	Rudder	--	Hawsers and Warps <u>7 ho</u>	--
Deck (Bottom) and Counter	--	Copper (or Y.M.) When put on	--	Standing & Running Rigging	--
Engine Room Skylights	<u>Good</u>	(State if on Felt.)			
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Cement (if Iron Ship) <u>1877</u>	<u>Good</u>		
Scuppers	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>		
Cargo and Main Hatchways	<u>Good</u>				
Hatches	<u>Good</u>				

General Observations, Opinion as to Class, &c.
 She is now in good condition and in our opinion eligible to continue as Classed

Wm B. Davy
John H Heck.

The Amount of Entry Fee ... £ 4 : 0 : 0 received by me, } 7.7.8
 Special ... £ 1 : 1 : 0 } 27.1.1883
 Certificate (if required) }
 to be sent as per margin... } £ : : }

Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £)
 Committee's Minute Friday, 20th January 1883.
 Character assigned 100A
JRM



The surveys are requested not to write on or over the margin of the minute.

(Insert Character precisely as in Register Book.)

LON 669-0504