

ANNUAL SURVEYS.

42164

No. 7 Survey held at London Date, first Survey 8 Jan^y Last Survey 24th Jan^y 1883
 No. in on the Iron Barque "Haddington" Master Fisher (No. of Visits)
 g. Book. 7 Tonnage 1206 Built at Liverpool When built 1846 Year. Month.
 Net 1206 Gross 1271 Under Dk. 1271 By whom built Owners C. F. Ellis. & B. Hatfield
 Port belonging to London Destined Voyage Algoa Bay.
 If Surveyed Afloat or in Dry Dock Afloat in the London Docks. (State Name of Dock.)

Last Survey, No. 40678 Port of London Classed S.L. Lon. N^o 3-81 Years assigned. 7.81 Character in Register Book. A.1.

Present Condition of the
 Decks good Treennails Rivets — good
 Waterways D^o Breasthooks and Stemson D^o
 Comings D^o Transoms, Pointers, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
 Planksheers D^o Keelsons D^o
 Sheerstrakes D^o Clamps and Shelves
 Topsides D^o Ceiling D^o
 Wales D^o Rudder D^o
 Plank (Bottom) and Counter Plating D^o Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
 Caulking of Bottom, Deck, & Waterways good Standing and Running Rigging D^o

General Observations, Opinion as to Class, &c. One plate of the sheerstrakes renewed on the port side aft of one bulwark plate there efficiently repaired & one length of bulwark rail renewed. The lining right aft in the tween decks removed and the inside there cleaned & coated. This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute Tuesday 30th January, 1883. J. H. Truscott.
 Character assigned A.1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master (No. of Visits)
 Reg. Book. Year. Month.
 Tonnage Built at When built
 Net Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the
 Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 Caulking of Bottom, Deck, & Waterways Standing and Running Rigging

General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18