

# ANNUAL SURVEYS.

42168

No.            Survey held at London Date, first Survey 13 Jan'y Last Survey 27 Jan'y 1883  
 (Received at London Office, 30.1.83)  
 No. in Reg. Book. on the BK Allora Master J. J. Phillips  
440 Net 1125 Built at Glasgow When built 1876 Month. 5  
 Tonnage Gross 1186 Under Dk. 1056 By whom built Bailey, Cook & Co Owners Foley & Co  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Blackwall Pt. & R. afloat  
(State Name of Dock.)

Last Survey, No. 41285 Port of Lon.  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good Windlass and Capstan Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good Pumps Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good Boats Good  
 Planksheers Good Keelsons Good Masts, Yards, &c. Good  
 Sheerstrakes Good Clamps and Shelves Good Condition, how ascertained From Str  
 Topsides Good Ceiling Good Sails Good  
 Wales Good Rudder Good Anchors, No. of 3 Nos. 12 & 14 lbs  
 Plank (Bottom) and Counter Good Copper or Y.M. Canted When put on new Cables Part on Str  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom & Canted.  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 2nd Feb. 1883. Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Character assigned TRW 100A Certificate (if required, to be sent as per margin) Paid 18

No.            Survey held at London Date, first Survey 10th Jan'y Last Survey 22nd Jan'y 1883  
 (No. of Visits           )  
 No. in Reg. Book. on the S Loch Ranza Master J. Boyd  
558 Net 1075 Built at Glasgow When built 1875 Month. 12  
 Tonnage Gross 1129 Under Dk. 1011 By whom built C. Bunnell & Co Owners J. R. Wilson  
 Port belonging to Glasgow Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Str & afloat  
(State Name of Dock.)

Last Survey, No. 40891 Port of Lon.  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways Good Breasthooks and Stemson Good Windlass and Capstan Good  
 Comings Good Transoms, Pointers, and Crutches Good Pumps Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good Boats Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good Masts, Yards, &c. Part new  
 Planksheers Good Keelsons Good Condition, how ascertained From Str  
 Sheerstrakes Good Clamps and Shelves Good Sails Good  
 Topsides Good Ceiling Good Anchors, No. of 3 Nos. 12 & 14 lbs  
 Wales Good Rudder Good Cables Part on Str  
 Plank (Bottom) and Counter Good Copper or Y.M. Canted When put on new Hawasers and Warps Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom & Canted.  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 2nd Feb. 1883. Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Character assigned TRW 100A Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minutes

Insert Character precisely as in Register Book.



L02669-0543