

ANNUAL SURVEYS.

42186

Survey held at London

Date, first Survey 8th Jan

(Received at London Office, 24.1.83)

Last Survey 9th Jan

1883

No. in Reg. Book. on the Iron Slew "Congella"

Master R. Pittwood

(No. of Visits)

Year.

Month.

Tonnage { Net 1041
Gross 1597
Under Dk. 1569

Built at Sunderland

When built 1881

12th

By whom built W. Doxford & Co.

Owners Bullard, King & Co

Port belonging to London

Destined Voyage

If Surveyed Afloat or in Dry Dock In the Bridge Dry Dock.
(State Name of Dock.)

Last Survey, No. 47613 Port of Lon

Classed

Years assigned.

Character in Register Book.

100 A.1.

6, 82

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails good Rivets good

Breasthooks and Stemson good

Transoms, Pointers, and Crutches good

Timbers of the Frame at the Openings good

Ditto ditto at other places good

Keelsons good

Clamps and Shelves

Ceiling good

Rudder good

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways good

Windlass and Capstan good

Pumps good

Boats good

Masts, Yards, &c. good

Condition, how ascertained from the deck

Sails good

Anchors, No. of 3. B. 15. 2 K

Cables good

Hawsers and Warps good

Standing and Running Rigging good

Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good.

The bottom has been examined and coated. A large number of rivets in the stern post renewed. This vessel is in good and efficient condition & eligible in my opinion to remain as classed.

Tuesday, 6th February, 1883.

J. H. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

No. Survey held at

Date, first Survey

Last Survey

18

No. in Reg. Book. on the

Master

Year.

Month.

Tonnage { Net
Gross
Under Dk.

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock.)

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

Committee's Minute

18


Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18



© 2021

Lloyd's Register Foundation

(The Surveyors are requested not to write on or over the margin.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

LON 669-0567