

ANNUAL SURVEYS.

No. 586 Survey held at London Date, first Survey 19th June Last Survey 24th June 18 83
No. in Reg. Book. 586 on the SS Sikh Master Johnson
Tonnage { Net 1510 Built at Glasgow When built 1880 Month. 11
Gross 2308
Under Dk. 2180 By whom built Atken & Mansel Owners Gellatley Hankey Seiverd & Co
Port belonging to Glasgow Destined Voyage Australia
If Surveyed Afloat or in Dry Dock Albert by South & Aspinall
(State Name of Dock.)


Last Survey, No. 41657 Port of London Classed 100 A. 8.82
Present Condition of the
Decks Good Treennails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c. Bottom & coated.
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday, 16th February, 1883. Senhouse Martindale
Character assigned 100 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage { Net Built at When built Year. Month.
Gross
Under Dk. By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
Present Condition of the
Decks Treennails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

LON 669-0609

