

ANNUAL SURVEYS.

42231

Survey held at London Date, first Survey 12 Feb Last Survey 12 Feb 1883  
in on the Iron Screw Helge Master L. Lerche  
Tonnage { Net 527 Built at Renfrew When built 1869 Month 5  
Gross 849  
Under Dk. 638 By whom built Andron. Clbrn Owners Steamship Co (Danmark)  
Port belonging to Copenhagen Destined Voyage Russia  
If Surveyed Afloat or in Dry Dock Afloat in the Commercial Docks

Last Survey, No. 772 Port of Antwerp

Present Condition of the  
Decks good Treennails Rivets good  
Waterways D- Breasthooks and Stemson good  
Comings D- Transoms, Pointers, and Crutches  
Upper Deck Beams & Fastenings Timbers of the Frames at the Openings  
Lower Deck Beams & Fastenings not exam Ditto ditto at other places  
Planksheers good Keelsons  
Sheerstrakes D- Clamps and Shelves  
Topsides D- Ceiling  
Wales D- Rudder good  
Plank (Bottom) and Counter D- Copper or Y.M. When put on  
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. It appears from Report No 772 of survey held at Antwerp in August 82 that a part of the special survey No 3 was then held. This vessel was visited by me on the 12 Feb 83 in the Commercial Docks where she was discharging a cargo of grain but the Master not being on board - a letter, copy of which is attached was addressed to him & attached is also his reply in regard to the special survey No 3. This case is respectfully submitted for the consideration of the Committee.

Committee's Minute Friday, 16th February, 1883.  
Character assigned Deformed A 1 J. H. Truscott.  
Certificate (if required, to be sent as per margin) Paid 18

No. Letter Survey held at Date, first Survey Last Survey 18  
No. in Reg. Book. on the 109/2/103 12  
Tonnage { Net Built at 71 year before  
Gross When built  
Under Dk. By whom built Owners  
Port belonging to Destined Voyage  
If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed  
Present Condition of the  
Decks Treennails  
Waterways Breasthooks and Stemson  
Comings Transoms, Pointers, and Crutches  
Deck Beams & Fastenings Timbers of the Frame at the Openings  
Deck Beams & Fastenings Ditto ditto at other places  
Keelsons  
Clamps and Shelves  
Ceiling  
Rudder  
Copper or Y.M. When put on  
Caulking of  
Bottom, Deck, & Waterways  
Windlass and Capstan  
Pumps  
Boats  
Masts, Yards, &c.  
Condition, how ascertained  
Sails  
Anchors, No. of  
Cables  
Hawsers and Warps  
Standing and Running Rigging  
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
General Observations, Opinion as to Class, &c.

Committee's Minute 18  
Character assigned  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18